

## Call Report

## RESIDENTS WELFARE ASSOCIATION TOWNSHIP - GURJINDER VIHAR - Apr 2025

Report Created: 05/05/25 14:01:56

## **SELECTED FILTERS**

Date Range:	Apr 2025	Offices:	All accessible offices
Country Regions:	India Country Region	Buildings:	RESIDENTS WELFARE ASSOCIATION TOWNSHIP - GURJINDER VIHAR
Regions:	North	Service Providers:	All non-competitors
Branches:	Noida	Technicians Branches:	Noida

## CALL REPORT SUMMARY - RESIDENTS WELFARE ASSOCIATION TOWNSHIP - GURJINDER VIHAR - APR 2025

UNIT	BANK	SWP	STOPPED	RUNNING	CANCELLED	NO FAULT/INTERFERENCE	REAL CALLS	TOTAL CALLS
> 2-13-S15975	All	0	0	1	0	1	0	1
> 2-13-S15976	All	0	1	0	0	1	0	1
> 2-13-S15977	All	0	1	0	0	0	1	1
> 2-13-S15978	All	0	0	1	1	0	0	1
> 2-13-S15979	All	0	0	2	0	0	2	2
> 2-13-S15980	All	0	1	1	1	0	1	2
> 2-13-S15981	All	0	1	2	0	0	3	3
> 2-13-S15982	All	0	0	1	0	0	1	1
> 2-13-S15983	All	0	0	2	0	1	1	2
> 2-13-S15984	All	0	1	1	0	0	2	2
> 2-13-S15985	All	0	1	2	0	0	3	3
> 2-13-S15986	All	0	0	2	1	1	0	2
> 2-13-S15987	All	0	0	0	0	0	0	0
> 2-13-S15988	All	0	0	4	0	2	2	4
> 2-13-S15989	All	0	0	0	0	0	0	0
> 2-13-S15990	All	0	0	1	0	1	0	1
> 2-13-S15991	All	0	0	1	0	0	1	1
> 2-13-S15992	All	0	0	0	0	0	0	0
> 2-13-S15993	All	0	0	1	0	0	1	1
> 2-13-S15994	All	0	0	1	0	1	0	1
> 2-13-S15995	All	0	0	0	0	0	0	0

> 2-13-S15996	All	0	0	1	0	0	1	1
> 2-13-S15997	All	0	0	1	0	0	1	1
> 2-13-S15998	All	0	0	0	0	0	0	0
> 2-13-S15999	All	0	0	0	0	0	0	0
> 2-13-S16000	All	0	2	0	0	1	1	2
> 2-13-S16001	All	0	1	0	0	0	1	1
> 2-13-S16002	All	0	0	0	0	0	0	0
> 2-13-S16003	All	0	0	0	0	0	0	0
> 2-13-S16004	All	0	0	1	1	0	0	1
> 2-13-S16005	All	0	0	0	0	0	0	0
> 2-13-S16006	All	0	1	1	0	1	1	2
> 2-13-S16007	All	0	0	1	1	0	0	1
> 2-13-S16008	All	0	0	1	0	0	1	1
> 2-13-S16009	All	0	1	0	0	0	1	1
> 2-13-S16010	All	0	0	0	0	0	0	0
> 2-13-S16011	All	0	0	0	0	0	0	0
> 2-13-S16012	All	0	1	1	0	0	2	2
> 2-13-S16013	All	0	2	1	0	0	3	3
> 2-13-S16014	All	0	0	0	0	0	0	0
> 2-13-S16015	All	0	0	3	0	1	2	3
> 2-13-S16016	All	0	1	1	0	1	1	2
> 2-13-S16017	All	1	2	1	0	1	2	3
> 2-13-S16018	All	0	0	1	0	1	0	1
> 2-13-S16019	All	0	0	1	0	0	1	1
> 2-13-S16020	All	1	1	3	0	1	3	4
> 2-13-S16021	All	0	1	1	1	0	1	2
> 2-13-S16022	All	1	1	0	0	0	1	1
> 2-13-S16023	All	0	1	0	0	0	1	1
> 2-13-S16024	All	0	0	0	0	0	0	0
> 2-13-S16025	All	0	2	2	2	0	2	4
> 2-13-S16026	All	0	1	0	0	0	1	1
> 2-13-S16027	All	0	1	0	0	1	0	1
> 2-13-S16028	All	0	0	1	0	1	0	1
> 2-13-S16029	All	0	0	0	0	0	0	0
> 2-13-S16030	All	0	2	0	0	0	2	2
> 2-13-S16031	All	0	0	0	0	0	0	0
> 2-13-S16032	All	0	1	0	0	0	1	1
> 2-13-S16033	All	0	0	1	1	0	0	1

> 2-13-S16034	All	0	0	0	0	0	0	0
> 2-13-\$16035	All	0	0	1	1	0	0	1
> 2-13-S16036	All	0	1	2	1	0	2	3
> 2-13-S16037	All	0	1	2	0	1	2	3
> 2-13-S16038	All	0	1	2	0	0	3	3
> 2-13-S16039	All	0	1	1	1	0	1	2
> 2-13-S16040	All	0	2	1	0	0	3	3
> 2-13-S16041	All	0	0	5	0	1	4	5
> 2-13-S16042	All	0	0	1	0	0	1	1
> 2-13-S16043	All	0	0	0	0	0	0	0
> 2-13-S16044	All	0	0	0	0	0	0	0
> 2-13-S16045	All	0	1	1	0	1	1	2
> 2-13-S16046	All	0	0	0	0	0	0	0
> 2-13-S16047	All	0	0	2	1	0	1	2
> 2-13-S16048	All	0	0	0	0	0	0	0
> 2-13-S16049	All	0	0	1	0	0	1	1
> 2-13-S16050	All	0	0	2	0	0	2	2
> 2-13-S16051	All	0	1	0	0	0	1	1
> 2-13-S16052	All	0	0	0	0	0	0	0
> 2-13-\$16053	All	0	0	0	0	0	0	0
> 2-13-S16054	All	0	0	0	0	0	0	0
> 2-13-S16055	All	0	1	1	1	0	1	2
> 2-13-S16056	All	0	0	1	0	0	1	1
> 2-13-S16057	All	0	0	0	0	0	0	0
> 2-13-S16058	All	0	1	1	0	0	2	2
> 2-13-S16059	All	0	0	0	0	0	0	0
> 2-13-S16060	All	0	0	0	0	0	0	0
> 2-13-S16061	All	0	0	4	0	0	4	4
> 2-13-S16062	All	0	0	0	0	0	0	0
> 2-13-S16063	All	0	0	0	0	0	0	0
> 2-13-S16064	All	0	0	0	0	0	0	0
> 2-13-S16065	All	0	0	0	0	0	0	0
> 2-13-S16066	All	0	0	2	0	0	2	2
> 2-13-S16067	All	0	1	0	0	0	1	1
> 2-13-S16068	All	0	0	0	0	0	0	0
> 2-13-S16069	All	1	1	1	1	0	1	2
> 2-13-S16070	All	0	0	0	0	0	0	0
> 2-13-S16071	All	0	1	0	0	0	1	1
								2

> 2-13-S16072	All	1	2	0	0	0	2	2
> 2-13-S16073	All	0	0	0	0	0	0	0
> 2-13-S16074	All	0	0	0	0	0	0	0
> 2-13-S16075	All	0	1	3	1	1	2	4
> 2-13-S16076	All	0	0	2	0	0	2	2
> 2-13-S16077	All	0	0	2	1	0	1	2
> 2-13-S16078	All	0	0	2	0	0	2	2
> 2-13-S16079	All	0	2	1	0	0	3	3
> 2-13-S16080	All	0	2	2	1	0	3	4
> 2-13-S16081	All	1	1	0	0	1	0	1
> 2-13-S16082	All	0	0	3	1	0	2	3
> 2-13-S16083	All	0	0	0	0	0	0	0
> 2-13-S16084	All	0	0	1	0	0	1	1
> 2-13-S16085	All	0	1	1	0	0	2	2
> 2-13-S16086	All	0	0	0	0	0	0	0
> 2-13-S16087	All	0	0	0	0	0	0	0
> 2-13-S16088	All	0	0	2	1	0	1	2
> 2-13-S16089	All	0	0	1	0	0	1	1
> 2-13-S16090	All	0	0	0	0	0	0	0
> 2-13-S16091	All	0	0	4	1	1	2	4
> 2-13-S16092	All	0	0	1	0	0	1	1
> 2-13-S16093	All	0	0	2	0	0	2	2
> 2-13-S16094	All	0	0	4	2	1	1	4
> 2-13-S16095	All	1	1	3	0	0	4	4
> 2-13-S16096	All	0	1	1	0	0	2	2
> 2-13-S16097	All	0	0	0	0	0	0	0
> 2-13-S16098	All	0	0	0	0	0	0	0
> 2-13-S16099	All	0	0	5	0	0	5	5
> 2-13-S16100	All	0	0	2	1	0	1	2
> 2-13-S16101	All	0	0	2	0	0	2	2
> 2-13-S16102	All	0	0	1	1	0	0	1
> 2-13-S16103	All	0	0	0	0	0	0	0
> 2-13-S16104	All	0	1	0	0	0	1	1
> 2-13-S16105	All	0	0	2	1	0	1	2
> 2-13-S16106	All	0	2	4	0	0	6	6
> 2-13-S16107	All	1	1	2	0	1	2	3
> 2-13-S16108	All	0	0	1	0	0	1	1
> 2-13-S16109	All	0	1	0	0	0	1	1
								-

TOTAL		8	71	158	32	28	169	229
> 2-13-S16136	All	0	0	0	0	0	0	0
> 2-13-S16135	All	0	0	2	0	0	2	2
> 2-13-S16134	All	0	0	0	0	0	0	0
> 2-13-S16133	All	0	0	1	0	0	1	1
> 2-13-S16132	All	0	0	0	0	0	0	0
> 2-13-S16131	All	0	0	0	0	0	0	0
> 2-13-S16130	All	0	0	0	0	0	0	0
> 2-13-S16129	All	0	0	0	0	0	0	0
> 2-13-S16128	All	0	1	2	0	0	3	3
> 2-13-S16127	All	0	2	2	1	0	3	4
> 2-13-S16126	All	0	0	1	0	0	1	1
> 2-13-S16125	All	0	0	2	0	1	1	2
> 2-13-S16124	All	0	2	0	0	0	2	2
> 2-13-S16123	All	0	1	2	0	1	2	3
> 2-13-S16122	All	0	2	1	0	0	3	3
> 2-13-S16121	All	0	1	3	0	0	4	4
> 2-13-S16120	All	0	2	5	3	1	3	7
> 2-13-S16119	All	0	0	2	1	0	1	2
> 2-13-S16118	All	0	1	0	0	0	1	1
> 2-13-S16117	All	0	0	0	0	0	0	0
> 2-13-S16116	All	0	0	0	0	0	0	0
> 2-13-S16115	All	0	0	0	0	0	0	0
> 2-13-S16114	All	0	0	1	1	0	0	1
> 2-13-S16113	All	0	0	1	0	0	1	1
> 2-13-S16112	All	0	1	1	0	0	2	2
> 2-13-S16111	All	0	0	0	0	0	0	0
> 2-13-S16110	All	0	1	1	0	0	2	2

 ${\it CALL\ REPORT-RESIDENTS\ WELFARE\ ASSOCIATION\ TOWNSHIP-GURJINDER\ VIHAR\ - APR\ 2025 }$ 

CALL **LOGGED** (CALLER) PROBLEM CUSTOM **ER UNIT** DATE **CONFIRM** OUT (NO.) FAULT **STP SWP** A/H NOF REC MAX SWPOA CHG CC REJ DOCKET **SWP REL** (NO.) FAULT CAUSE IN (NO.) FAULT ACTION CONTACT TIME **RESPONSE** (TECHNICIAN) **LIFTUSA** IS **STOPPED** TIME **ACTION** MATERIA GE L USED SWP - Stuck With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - No Fault, CC - Call cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls Lift No. All > .132 GR STP **SWP** A/H NOF REC SWPOA CHG CC MAX REJ  $\square$ 1179629 (Vinod gupta ) Lift not 144 GR 13:10 working (2-13)-S16119) -Elevator> MR>Gear ed 06/04/25 06/04/25 14:03 06/04/25 14:21 (E1) C.O.P.-Buttons/Keyswitches/ Indicators/Display/P СВ INDIA4361239 06/04/25 14:05 (K2) Communication Fault (A6) Replaced Component 9990727731, 55.0 Minutes (Aasif.) E1: K2: A6 Yes 8920799565 C.O.P.-Buttons/Keyswitches/ Indicators/Display/P Communication Fault Lift was working condition ok but 13th floor lop display not working, Now new display replace now working condition ok complaint done, Lift No. All > .133 GR **SWP** A/H NOF REC STP MAX SWPOA CHG CC REJ 1187329 11:42 (sharma) lift is not working  $\mathbf{M}$ 30/04/25 Cust omer canc el call 9719555653, 0 (Raja .) :: No 9719555653

		,	ER UNIT							
CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA				
IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	l							
TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
							ıble, N	OF - N	lo	
I GR					STP MAX	SWP SWPOA		-		
09:35		(navin) Lift stuck every time	1 GR (2-13 -S16006) - Elevator> MR>Gear ed						I = = =	
27/04/25 09:5	57 27/04/25 11:0	` '								
8 27/04/25 09:8	58	(K7) Component or Connection - Loose (A1) Adjusted / Repaired								
	23.0 Minutes	Contactor/Relay/Times Component or Connection - Loose Lift was not working, Main drive trip bk not opening. Now bk contactor wiring check and coil clean now lift								
	IN  TIME STOPPED  With Passenge all cancelled, S  GR  09:35	IN SWP REL  TIME RESPONSE STOPPED TIME  With Passengers, SWPOA - Studil cancelled, STP - Stopped, R  GR  09:35  27/04/25 09:57 27/04/25 11:09 8 27/04/25 09:58	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) ACTION  With Passengers, SWPOA - Stuck With Passengers Or all cancelled, STP - Stopped, REC - Only VFM Received  GR  09:35 (navin) Lift stuck every time  27/04/25 09:57 27/04/25 11:05 (C3) Contactor/Relay/Times  8 27/04/25 09:58 (K7) Component or Connection - Loose (A1) Adjusted / Repaired  23.0 Minutes (Raja.) C3: K7: A1 Contactor/Relay/Times Component or Connection - Loose Lift was not working, Main drive trip bk not opening. Now bk contactor wiring check	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS MATERIA L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/Fall cancelled, STP - Stopped, REC - Only VFM Received Calls, REC.  GR  09:35 (navin) Lift stuck 1 GR every time (2-13 - S16006) - Elevator MR>Gear ed  27/04/25 09:57 27/04/25 11:05 (C3) Contactor/Relay/Timer  8 27/04/25 09:58 (K7) Component or Connection - Loose (A1) Adjusted / Repaired  23.0 Minutes (Raja.) C3: K7: A1 No Contactor/Relay/Timer Component or Connection - Loose  Lift was not working, Main drive trip bk not opening. Now bk contactor wiring check and coil clean now lift	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA ACTION MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hou all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Received Calls, Receiv	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Reject MAX  09:35 (navin) Lift stuck 1 GR every time (2-13 - S16006) - Elevator > MR>-Gear ed  27/04/25 09:57 27/04/25 11:05 (C3) Contactor/Relay/Timer  8 27/04/25 09:58 (K7) Component or Connection - Loose (A1) Adjusted / Repaired  23.0 Minutes (Raja.) C3: K7: A1 No Contactor/Relay/Timer Component or Connection - Loose  Lift was not working, Main drive trip bk not opening. Now bk contactor wiring check and coil clean now lift	IN SWP REL (No.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA ACTION MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargea all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  GR STP SWP MAX SWPOA  09:35 (navin) Lift stuck every time (2-13 - S16006) - Elevator> MR-Gear ed  27/04/25 09:57 27/04/25 11:05 (C3) Contactor/Relay/Timer  8 27/04/25 09:58 (K7) Component or Connection - Loose (A1) Adjusted / Repaired  23.0 Minutes (Raja.) C3: K7: A1 No Contactor/Relay/Timer Component or Connection - Loose Lift was not working, Main drive trip bk not opening. Now bk contactor wiring check and coil clean now lift	CONFIRM OUT (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA ACTION MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, No all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  GR  STP SWP A/H MAX SWPOA CHG  09:35  (navin) Lift stuck 1 GR every time (2-13 -\$16006) - Elevator> MR>Gear ed  27/04/25 09:57 27/04/25 11:05 (C3) Contactor/Relay/Timer  8 27/04/25 09:58  (K7) Component or Connection - Loose (A1) Adjusted / Repaired  23.0 Minutes (Raja.) C3: K7: A1 No Contactor/Relay/Timer Component or Connection - Loose Lift was not working, Main drive trip bk not opening. Now bk contactor wiring check and coil clean now lift	CONFIRM OUT	CONFIRM   OUT   (NO.) FAULT CAUSE   (NO.) FAULT CAUSE   (NO.) FAULT CAUSE   (NO.) FAULT ACTION   IS   LIFTUSA   MATERIA   GE   LUSED   STOPPED   TIME   RESPONSE   (TECHNICIAN)   IS   LUSED   STOPPED   TIME   ACTION   MATERIA   GE   LUSED   STOPPED   TIME   TI

under observation....

(CALLER) PROBLEM CUSTOM

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	I							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	able, N	OF - 1	No	
1186490	19:46		(Colonel Sandip Chopra) 9968852961 Lift not working.	1 GR (2-13 -S16006) - Elevator> MR>Gear ed		_		_ ₩	[ ₩	1 <sup>-</sup> 0	
27/04/25	27/04/25 21:	33 27/04/25 23:3	6 (EX) Lift Car - Other					₹		]	
INDIA441505	7 27/04/25 23:	13	(KZ) Running at Arrival and No Fault Found (AX) Action - Other								
9968852961, 9968852961	3.8 Hours	3.5 Hours	(Hovendra Kumar) EX: KZ: AX Lift Car - Other Running at Arrival and No Fault Found  Lift running on arrival when I reached on site i am check lift 15 minutes running time no issue	No							

CALL

OALL	LOGGED		(OALLER) I ROBLE	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTIO								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		cuck With Passengers C REC - Only VFM Receiv				_	able, No	OF - 1	No	
Lift No. All > 1	00 GR					STP MAX	SWP SWPOA	A/H CHG		REC	
1179264	10:35		(rahul) fan not workin	g 100 GR (2-13 -S16076) - Elevator> MR>Gear ed						] 2	
05/04/25	05/04/25 11:2	27 05/04/25 11:4	8 (CF) Controller Ventilation -Fan/Filter/Vent							]	
INDIA435906	9 05/04/25 11:4	10	(K1) Burnt Out (A6) Replaced Component								
6398892009, 6398892009		1.1 Hours	(Rajkumar Singh) CF: K1: A6 Controller Ventilation -Fan/Filter/Vent Burnt Out Lift was working but	= No							
			Lit was working but								

fen check fen waring check fen is born

CALL

			ER UNIT						
CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			
IN	SWP REL								
TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
_						_	ıble, N	OF - N	lo
11:02		(Rohit) Lift fan not work	100 GR (2-13 -S16076) - Elevator> MR>Gear ed						I¯Ø¯
09/04/25 11:4	45 09/04/25 12:4	3 (EX) Lift Car - Other					_		I <sup>-</sup>
6 09/04/25 12:0	08	(K4) Component Damaged / Broken / Stripped (AX) Action - Other							
	1.1 Hours	/ Broken / Stripped  Lift was working Fault. Car cavin fan not working Action. Car cavin fan not working inform to							
	IN  TIME STOPPED  With Passenge all cancelled, S  11:02	IN SWP REL  TIME RESPONSE STOPPED TIME  With Passengers, SWPOA - Stall cancelled, STP - Stopped, R  11:02  09/04/25 11:45 09/04/25 12:46 6 09/04/25 12:08	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) ACTION  With Passengers, SWPOA - Stuck With Passengers Or all cancelled, STP - Stopped, REC - Only VFM Received  11:02 (Rohit) Lift fan not work  09/04/25 11:45 09/04/25 12:43 (EX) Lift Car - Other  6 09/04/25 12:08 (K4) Component Damaged / Broken / Stripped (AX) Action - Other  1.1 Hours (Hovendra Kumar) EX : K4 : AX Lift Car - Other Component Damaged / Broken / Stripped  Lift was working Fault. Car cavin fan not working Action. Car cavin fan not working inform to	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS MATERIA L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/Fall cancelled, STP - Stopped, REC - Only VFM Received Calls, REC.  11:02 (Rohit) Lift fan not work (2-13 - S16076) - Elevator MR>Gear ed  09/04/25 11:45 09/04/25 12:43 (EX) Lift Car - Other  6 09/04/25 12:08 (K4) Component Damaged / Broken / Stripped (AX) Action - Other  1.1 Hours (Hovendra Kumar) No EX : K4 : AX Lift Car - Other Component Damaged / Broken / Stripped  Lift was working Fault. Car cavin fan not working Action. Car cavin fan not working inform to customer mr.prashant	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA ACTION MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hou all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM work (2-13 - S16076) - Elevator> MR>Gear ed  11:02 (Rohit) Lift fan not 100 GR work (2-13 - S16076) - Elevator> MR>Gear ed  09/04/25 11:45 09/04/25 12:43 (EX) Lift Car - Other  6 09/04/25 12:08 (K4) Component Damaged / Broken / Stripped (AX) Action - Other  1.1 Hours (Hovendra Kumar) No EX : K4 : AX Lift Car - Other Component Damaged / Broken / Stripped  Lift was working Fault. Car cavin fan not working Action. Car cavin fan not working inform to customer mr, prashant	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Reject (2-13 - S16076) - Elevator - MR>Gear ed  11:02 (Rohit) Lift fan not 100 GR (2-13 - S16076) - Elevator - Elevator - MR>Gear ed  09/04/25 11:45 09/04/25 12:43 (EX) Lift Car - Other  6 09/04/25 12:08 (K4) Component Damaged / Broken / Stripped (AX) Action - Other  1.1 Hours (Hovendra Kumar) No EX : K4 : AX Lift Car - Other Component Damaged / Broken / Stripped  Lift was working Fault. Car cavin fan not working Action. Car cavin fan not working Action. Car cavin fan not working inform to customer mr.prashant	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargea all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  11:02 (Rohit) Lift fan not working Fault. Car - Other  (K4) Component Damaged / Broken / Stripped (AX) Action - Other  1.1 Hours (Hovendra Kumar) No EX : K4 : AX Lift Car - Other Component Damaged / Broken / Stripped Lift was working Fault. Car cavin fan not working Action. Car cavin fan not working inform to customer mr.prashant	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA ACTION MATERIA GE LUSE)  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, No all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  11:02 (Rohit) Lift fan not 100 GR (2-13 - S16076) - Elevator > MR > Gear ed  09/04/25 11:45 09/04/25 12:43 (EX) Lift Car - Other  6 09/04/25 12:08 (K4) Component Damaged / Broken / Stripped (AX) Action - Other  1.1 Hours (Hovendra Kumar) No EX : K4 : AX Lift Car - Other Component Damaged / Broken / Stripped  Lift was working Fault. Car cavin fan not working Action. Car cavin fan not working inform to customer mr.prashant	CONFIRM OUT (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA ACTION MATERIA GE LUSED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - Nall cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  11:02 (Rohit) Lift fan not work (2:13 - S16076) - Elevator> MR>Gear ed  09/04/25 11:45 09/04/25 12:43 (EX) Lift Car - Other  1.1 Hours (Hovendra Kumar) Stripped (AX) Action - Other  1.1 Hours (Hovendra Kumar) Ex: K4 : AX Lift Car - Other Component Damaged / Broken / Stripped Lift was working Fault. Car cavin fan not working Action. Car cavin fan not working inform to customer mr.prashant

cavin fan shortly

(CALLER) PROBLEM CUSTOM

CALL

CALL	LOGGED		(CALLER) PROBLEM	CUSTOM ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
			uck With Passengers O					ıble, N	OF - N	10	
Lift No. All > 1	102 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1179836	09:44		(App) 3P lift 102 Lifits issues • 3P-801 IN PROGRESS 03 Apr · Request ID 167233 Lift of 3P (No.102)not working properly,the doors are getting stuck, only half panel opening,happened yesterday evening, and today evening also. add_commentRaised by Babyla Gusain · Unit Level	102 GR (2-13 -S16078) - Elevator> MR>Gear ed							
07/04/25	07/04/25 10:0	05 07/04/25 12:1	6 (EB) Car mounted safety circuit component -Switch/Button								
INDIA436232	2 07/04/25 11:4	12	(K2) Communication Fault (A1) Adjusted / Repaired								
8447091893		2.0 Hours	(Aasif ., Sohan Veer Singh) EB : K2 : A1 Car mounted safety circuit component -Switch/Button Communication Fault	No							
			Lift working but sometimes door open in Between floor level Now cpu card and hardware card reconnect now lift working condition ok								

**ER UNIT** DATE **CONFIRM** OUT (NO.) FAULT STP **SWP** A/H NOF REC MAX SWPOA CHG CC REJ DOCKET **SWP REL** (NO.) FAULT CAUSE IN (NO.) FAULT ACTION CONTACT TIME **RESPONSE** (TECHNICIAN) **LIFTUSA** IS **STOPPED** TIME **ACTION** MATERIA GE L USED SWP - Stuck With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - No Fault, CC - Call cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls 1187385 14:54 (Balveer) Lift not 102 GR working (2-13)-S16078) -Elevator> MR>Gear ed 30/04/25 30/04/25 15:58 30/04/25 16:17 (D9) Gate Switch INDIA4423193 30/04/25 15:58 (K2) Communication Fault (A1) Adjusted / Repaired 6398892009 1.1 Hours (Rajkumar Singh) D9 Yes : K2 : A1 Gate Switch Communication Fault Lift was not working error code N/A Reason of failure 6th floor get lock problem Corrective action-now landing door male contect born contect new male contect replace elevator working now ok Lift No. All > 103 GR STP **SWP** A/H NOF REC MAX SWPOA CHG CC REJ  $\square$ 1182601 18:25 (Sahil) Not working 15/04/25 Cust omer canc el call 9311035115, 0 (Raja .) :: No 9311035115

(CALLER) PROBLEM CUSTOM

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O				_	ıble, N	OF - N	lo	
Lift No. All > 1	104 GR					STP MAX	SWP SWPOA			REC REJ	
1181142	09:02		(Navjot ) Lift not working	104 GR (2-13 -S16079) - Elevator> MR>Gear ed		<u> </u>					
11/04/25	11/04/25 09:3	5 11/04/25 10:2	7 (C3) Contactor/Relay/Time	r							
INDIA437262	3 11/04/25 09:3	6	(K2) Communication Fault (AX) Action - Other								
9968656672, 9968656672	1.4 Hours	34.0 Minutes	(Sanjay Verma) C3: K2: AX Contactor/Relay/Time Communication Fault Elevator stop at ground floor ground floor landing door contact problem contact clean elevator working fine	r							

CALL

CALL

(CALLER) PROBLEM CUSTOM CALL **LOGGED ER UNIT** A/H NOF REC DATE **CONFIRM** OUT (NO.) FAULT **STP SWP** MAX SWPOA CHG CC REJ DOCKET **SWP REL** (NO.) FAULT CAUSE IN (NO.) FAULT ACTION CONTACT TIME **RESPONSE** (TECHNICIAN) **LIFTUSA** IS **STOPPED** TIME **ACTION** MATERIA GE L USED SWP - Stuck With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - No Fault, CC - Call cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls Lift No. All > 105 GR STP **SWP** A/H NOF REC SWPOA CHG CC MAX REJ  $\square$ 1181599 13:01 105 GR (rahul) door issue (2-13)-S16080) -Elevator> MR>Gear ed 12/04/25 12/04/25 13:16 12/04/25 14:07 (D5) Door Operator -Motor / Gear Box / Belt / Chain / Static Drive INDIA4376302 12/04/25 13:16 (KN) Out of Adjustment / Alignment (AX) Action - Other 9627702352, 15.0 Minutes (Rajkumar Singh) D5 No 8920799565 : KN : AX Door Operator - Motor / Gear Box / Belt / Chain / Static Drive Out of Adjustment / Alignment Lifts was not working error code NA Reason of failure car door rope damage Corrective action-now car door rope new replace elevator working now 14:51 1181633 (rahul) not working 12/04/25 Cust omer canc el call 9627702352, 0 (Rajkumar Singh) : : No 8920799565

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	No
1184852	17:01		(Rahul ) not working.	105 GR (2-13 -S16080) - Elevator> MR>Gear ed		 Ø		_		]_67
22/04/25	22/04/25 17:1	2 22/04/25 17:5	9 (D1) Door Brake							
INDIA440137	6 22/04/25 17:5	6	(K2) Communication Fault (A1) Adjusted / Repaired							
9627702352, 9627702352	58.0 Minutes	55.0 Minutes	(Rajkumar Singh) D1 : K2 : A1 Door Brake Communication Fault Lift was working condition 5th floor landing door male contect replace elevator working now ok	Yes						

CALL

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	REC	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, No	OF - N	lo	
Lift No. All > 1	107 GR					STP MAX	SWP SWPOA	A/H CHG			
1178198	09:22		(vinod kumar) lift not working	107 GR (2-13 -S16082) - Elevator> MR>Gear ed							
02/04/25	02/04/25 09:4	40 02/04/25 10:4	2 (SX) Shaft - Other					_		]_[	
INDIA435059	0 02/04/25 10:′	11	(K2) Communication Fault (AX) Action - Other								
9634876726, 9634876726		49.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault Elevator stop at 8th floor Ground floor landing door contact problem door contact clean elevator working ok	No							

CALL

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	-		uck With Passengers O EC - Only VFM Receive				•	ible, N	OF - N	lo	
Lift No. All > 1	109 GR					STP MAX	SWP SWPOA			REC REJ	
1180076	19:34		(Subhash) Door issue	109 GR (2-13 -S16084) - Elevator> MR>Gear ed						]_8	
07/04/25	07/04/25 19:	42 07/04/25 20:1	7 (SX) Shaft - Other								
INDIA436434	1 07/04/25 20:	16	(K2) Communication Fault (AX) Action - Other								
8439826779, 8439826779		42.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault Car door open close time noise car door adjust noise removed	No							

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O				_	able, N	OF - N	lo
Lift No. All > 1	1 GR					STP MAX	SWP SWPOA			REC REJ
1177884	09:47		(Navin) lift not working	9 4 GR (2-13 -S16008) - Elevator> MR>Gear ed		<u> </u>				<u> </u>
01/04/25	01/04/25 17:	22 01/04/25 18:2	26 (T7) Machine Room Speed Encoder/Position Reference Encoder							
INDIA435012	1 01/04/25 18:	21	(K7) Component or Connection - Loose (A1) Adjusted / Repaired							
9871537634, 9871537634	8.7 Hours	8.6 Hours	(Rajkumar Singh) T7 : K7 : A1 Machine Room Speed Encoder/Position Reference Encoder Component or Connection - Loose  Lifts was not working problem lift some time sho ininspection mode controller nc point problem nc point is change and liftis working fine							

CALL

			(	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
			uck With Passengers Or EC - Only VFM Receive					ıble, N	OF - N	lo	
1181472	08:47		(siddharth) door issue	11 GR (2-13 -S15985) - Elevator> MR>Gear ed				_	ſ¯⊏	]¯፼¯	
12/04/25	12/04/25 09:2	28 12/04/25 11:0	7 (DA) Door Shoe Guides /Sill/Sill Bracket						I <sup>-</sup> C	l <sup>-</sup> 🗆	
INDIA437555	51 12/04/25 09:5	53	(K5) Component Dirty (A4) Cleaned								
8826266917		1.1 Hours	(Hovendra Kumar) DA: K5: A4 Door Shoe Guides /Sill/Sill Bracket Component Dirty  Lift was not working, and 2nd floor landing door stuck, check and found 2nd floor landing door sill stone								

now car sill clean lift working condition ok.

CALL

CALL

CALL	LOGGED		(CALLER) PROBLEM	ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O EC - Only VFM Receive				_	ble, N	OF - N	lo
1185709	10:53		(JAYAPRAKASH) LOP BUTTON NOT WORKING ON 8TH FLOOR	110. GR (2-13 -S16085) - Elevator> MR>Gear ed						_ _ _
25/04/25	25/04/25 11:1	0 25/04/25 12:1	5 (SX) Shaft - Other					_		
INDIA440869	5 25/04/25 11:5	58	(K2) Communication Fault (AX) Action - Other							
9719462451, 8920799565		1.1 Hours	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault 8th floor lop button not button repair lop	Yes						
			working							
Lift No. All > 1	12. GR						SWP SWPOA			REC REJ
1177853	08:43		(SURENDER KUMAR) LM.16125 AND 16126 BOTH LIFTS ARE NOT WORKING , KINDLY DO AS POSSIBLE	150 GR (2-13 -S16125) - Elevator> MR>Gear ed				$\square$		Ø
01/04/25	01/04/25 08:5	56 01/04/25 10:1	8 (SX) Shaft - Other							
INDIA434809	1 01/04/25 09:1	16	(K2) Communication Fault (AX) Action - Other							
7710040801		33.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault Elevator stop at 9th floor landing door							
			contact problem contact clean elevator working fine							

CALL

CALL	LOGGED		(CALLER) PROBLEM	CUSTOM ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	-		uck With Passengers O EC - Only VFM Receive				_	ble, N	OF - N	lo	
1182237	16:18		(Mohan) COP button not work							<sup>−</sup> Ø <sup>−</sup>	
14/04/25											
									Cust omer canc el cal		
9599344130, 9599344130	0		(Raja .) ::	No							
Lift No. All > 1	13. GR					STP MAX	SWP SWPOA		NOF CC	REC REJ	
1178047	15:37		( Mobile App) 4V lift 154 not working	154 GR (2-13 -S16129) - Elevator> MR>Gear ed		_				⊠	
01/04/25	01/04/25 15:	57 01/04/25 16:5	1 (DX) Door - Other					₹			
INDIA434944	4 01/04/25 15:	58	(K5) Component Dirty (A4) Cleaned	,							
8447091893, 8447091893	1.2 Hours	21.0 Minutes	(Hovendra Kumar) DX : K5 : A4 Door - Other Component Dirty	No							
			Door sencer spit doo	r							

sencer clean now elevator working ok

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA	A/H CHG		REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
			uck With Passengers O EC - Only VFM Receive					ble, NC	OF - N	lo	
1180679	16:15		(Mohan ) 9599344130 COP button not working.	113. GR (2-13 -S16106) - Elevator> MR>Gear ed						_⊠	
09/04/25	09/04/25 16:3	37 09/04/25 17:0	3 (S6) Floor PCB								
INDIA436878	3 09/04/25 16:4	16	(K2) Communication Fault (A6) Replaced Component								
9599344130, 8920799565		31.0 Minutes	(Rajkumar Singh) S6: K2: A6 Floor PCB Communication Fault Tower 4A lift no.113  Error code-N/A Reason of failure car cop button 11th 2st floor cop button not working Corrective action-now cop button 11th& 2st floor cop button new replace button								

CALL

adjust now lift working

condition ok

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	ļ.							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	•		uck With Passengers Or EC - Only VFM Receive				•	able, No	OF - N	lo	
Lift No. All > 1	14 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1179044	15:48		(Mobile App) 4A lift 113 Lift running Very slow speed and Door opening & Closing issue .	113. GR (2-13 -S16106) - Elevator> MR>Gear ed					_		
04/04/25	04/04/25 16:1	0 04/04/25 16:3	5 (EX) Lift Car - Other					$ \mathbf{Z} $			
INDIA435760	5 04/04/25 16:1	9	(KZ) Running at Arrival and No Fault Found (AX) Action - Other								
8447091893, 8447091893		31.0 Minutes	(Sohan Veer Singh) EX : KZ : AX Lift Car - Other Running at Arrival and No Fault Found Running on arrival No	No							

CALL

OALL	LOGGLD		(CALLER) I ROBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	lo	
1181700	19:39		(Das) Mantrap	114 GR (2-13 -S16107) - Elevator> MR>Gear ed				_ ₩	<sup>-</sup> -	I_⊠	
12/04/25	12/04/25 20:0	312/04/25 20:0	7 (C2) Circuit Protection-Circuit Breaker/Fuse/RCD/O verload							l <sup>-</sup>	
INDIA437783	2 12/04/25 20:0	3 2025-04-12 19:53:00	(K2) Communication Fault (A9) Switched Off for Repairs								
8750304444, 8750304444	28.0 Minutes	24.0 Minutes	(Raja .) C2 : K2 : A9 Circuit Protection-Circuit Breaker/Fuse/RCD/O verload Communication Fault								
			Mantrap rescue but lif under shutdown for checking	t							

Fault unknowns.

CALL

			,	ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - 1	No
1184769	13:33		(Dharmpal) lift not working	114 GR (2-13 -S16107) - Elevator> MR>Gear ed						]_8
22/04/25	22/04/25 13:	46 22/04/25 14:2	3 (EX) Lift Car - Other							]
INDIA440014	43 22/04/25 13:-	46	(K2) Communication Fault (AX) Action - Other							
9627274766, 9627274766		13.0 Minutes	(Sohan Veer Singh) EX: K2: AX Lift Car - Other Communication Fault Lift shutdown problem not solved I am working here	No						

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	10	
Lift No. All > 1	15. GR					STP MAX	SWP SWPOA			REC REJ	
1180895	11:43		(dharmapal) fan or display not working	115. GR (2-13 -S16108) - Elevator> MR>Gear ed						1¯⊠¯	
10/04/25	10/04/25 11:	54 10/04/25 13:0	4(E1) C.O.P Buttons/Keyswitches/ Indicators/Display/P CB							I <sup>-</sup> -	
INDIA437049	2 10/04/25 11:	54	(K5) Component Dirty (A4) Cleaned	,							
9627274766, 9627274766		11.0 Minutes	(Sohan Veer Singh) E1: K5: A4 C.O.P Buttons/Keyswitches/ Indicators/Display/P CB Component Dirty	No							
			Display working with problem Display wire reconnect and display re program button wire reconnect	,							

Working now

(CALLER) PROBLEM CUSTOM

CALL

8348491128, 0 (Hovendra Kumar) : No 8348491128 : omer canc el call

OALL	LOGGLD		(OALLEN) I NOBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC		
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
			uck With Passengers Or EC - Only VFM Receive					able, N	OF - N	lo	
Lift No. All >	18. GR					STP MAX	SWP SWPOA	A/H CHG	NOF CC	REC REJ	
1184988	08:50		(mohan) DISPLAY NOT WORKING, LIFT NOT WORKING PROPERLY	113. GR (2-13 -S16106) - Elevator> MR>Gear ed					[ <sup>-</sup>		
23/04/25	23/04/25 09:	11 23/04/25 09:5	0 (E1) C.O.P Buttons/Keyswitches/ Indicators/Display/P CB								
INDIA440203	1 23/04/25 09:	25	(K2) Communication Fault (A1) Adjusted / Repaired								
9599344130		35.0 Minutes	(Rajkumar Singh) E1: K2: A1 C.O.P Buttons/Keyswitches/ Indicators/Display/P CB Communication Fault Lift working but 13 th floor lop display not working, Check D' Connector cable wiring check and Display software change now Display working condition ok	Yes							
			Note :- this Display not working frim befire Contect	,							

CALL

working ok

CALL

Lift was not working, Due to power supply issues, power supply cut at mony times , now power reset lift work condition..... information to customer

CALL	LOGGED		(CALLER) PROBLEM	ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O				_	able, N	OF - N	lo
1185721	11:16		(Raaj Mani) Lift not working	120. GR (2-13 -S16091) - Elevator> MR>Gear ed					I <sup>-</sup> □	_4
25/04/25	25/04/25 11:2	27 25/04/25 13:0	2 (SX) Shaft - Other					✓		
INDIA440891	8 25/04/25 12:	16	(K2) Communication Fault (AX) Action - Other							
9205297304, 8920799565		1.0 Hour	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault	No						
			Elevator running on arrival foult not found							
Lift No. All > 1	21 GR					STP MAX	SWP SWPOA		NOF CC	REC REJ
1183394	09:07		(raj mani) not working	121 GR (2-13 -S16092) - Elevator> MR>Gear ed					I <sup>-</sup> -	-⊠
18/04/25	18/04/25 09:	18 18/04/25 11:1	5 (SX) Shaft - Other							
INDIA438996	8 18/04/25 10:2	29	(K2) Communication Fault (AX) Action - Other							
9205297304, 9205297304		1.4 Hours	(Sanjay Verma) SX : K2 : AX Shaft - Other Communication Fault	No						
			Elevator stop at 8th floor door not close close relay problem relay reconnect door close elevator working	3						

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	•		uck With Passengers O EC - Only VFM Receive				_	ıble, N	OF - N	0	
Lift No. All >	122. GR					STP MAX	SWP SWPOA			REC REJ	
1179748	21:24		(App) 4F lift 122 not working	122. GR (2-13 -S16109) - Elevator> MR>Gear ed		<u> </u>		_ \( \text{\ti}}\text{\tett{\text{\tetx{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\texi}\text{\text{\texi}\text{\text{\text{\texi}\text{\text{\texi}\text{\texi}\text{\text{\text{\text{\tet{\text{\text{\texi}\text{\text{\texi}\text{\texi}\texit{\t			
06/04/25	06/04/25 21:4	17 06/04/25 22:5	9 (SX) Shaft - Other								
INDIA436174	16 06/04/25 22:1	15	(K2) Communication Fault (A1) Adjusted / Repaired								
8447091893, 8447091893	1.6 Hours	51.0 Minutes	(Rajkumar Singh) SX: K2: A1 Shaft - Other Communication Fault Lift was not working problem car door roller new replace and car shoe adjust elevator working now ok	No							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	able, No	OF - N	0	
Lift No. All > 1	23. GR					STP MAX	SWP SWPOA		NOF CC		
1183695	09:37		(Badal) Lift not working	123. GR (2-13 -S16110) - Elevator> MR>Gear ed		<u> </u>				_ \( \overline{A} \)	
19/04/25	19/04/25 10:	05 19/04/25 11:5	9 (EX) Lift Car - Other								
INDIA439287	2 19/04/25 10::	26	(KN) Out of Adjustment / Alignment (A1) Adjusted / Repaired								
9555177520, 9555177520	2.4 Hours	49.0 Minutes	(Hovendra Kumar) EX : KN : A1 Lift Car - Other Out of Adjustment / Alignment	No							
			Lift was working but lift running time car sill tuch with latch roller now car sill gep maintain now lift								

working condition ok

(CALLER) PROBLEM CUSTOM

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	-		uck With Passengers O EC - Only VFM Receive				•	able, N	OF - N	No
1184747	12:31		(Sabuddin) lift not working	125 GR (2-13 -S16112) - Elevator> MR>Gear ed						]_8
22/04/25	22/04/25 12:3	36 22/04/25 13:5	4 (EX) Lift Car - Other							]
INDIA439999	4 22/04/25 13:	18	(K2) Communication Fault (AX) Action - Other							
6396592245, 6396592245		47.0 Minutes	(Pushpender Singh, Saurabh Kumar) EX : K2 : AX Lift Car - Other Communication Fault Lift not working so lift is shutdown due to problem not solve, work under process by team, we are checking this lift	No						

CALL

LOGGED		(OALLEN) MODELIN	ER UNIT						
CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA	-	_	_
IN	SWP REL								
TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
_		_				_	ble, N	OF - N	lo
26 GR					STP MAX	SWP SWPOA			
18:55		(Dhiraj ) lift not working	126 GR (2-13 -S16093) - Elevator> MR>Gear ed						
13/04/25 19:0	0213/04/25 19:4								
5 13/04/25 19:0	03	(K2) Communication Fault (A1) Adjusted / Repaired							
	8.0 Minutes	: K2 : A1 Hoistway Lock -Arms/Cams/Contacts /Lock Box/Lock Roller/Restrictor Communication Fault Lift is not working due to 4th floor door contact not connected properly, coor contact							
	CONFIRM  IN  TIME STOPPED  With Passenge all cancelled, S 26 GR  18:55	CONFIRM OUT  IN SWP REL  TIME RESPONSE TIME  With Passengers, SWPOA - Strall cancelled, STP - Stopped, R 26 GR  18:55	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) ACTION  With Passengers, SWPOA - Stuck With Passengers Or all cancelled, STP - Stopped, REC - Only VFM Received  18:55 (Dhiraj ) lift not working  13/04/25 19:02 13/04/25 19:48 (DC) Hoistway Lock -Arms/Cams/Contacts /Lock Box/Lock Roller/Restrictor  5 13/04/25 19:03 (K2) Communication Fault (A1) Adjusted / Repaired  8.0 Minutes (Saurabh Kumar) DC : K2 : A1 Hoistway Lock -Arms/Cams/Contacts /Lock Box/Lock Roller/Restrictor Communication Fault Lift is not working due to 4th floor door contact not connected.	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS MATERIA L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/Full cancelled, STP - Stopped, REC - Only VFM Received Calls, REC - Only VFM Received Calls, REC - Only VFM Received Calls, REC - Stopped, REC - Only VFM Received Calls, REC - Only VFM Received Call	CONFIRM OUT	CONFIRM OUT (NO.) FAULT STP MAX  IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Reject (2-13 S16093) - Elevators MR>Gear ed  13/04/25 19:02 13/04/25 19:48 (DC) Hoistway Lock - Arms/Cams/Contacts / Lock Box/Lock Roller/Restrictor  5 13/04/25 19:03 (K2) Communication Fault (A1) Adjusted / Repaired  8.0 Minutes (Saurabh Kumar) DC No: K2: A1 Hoistway Lock - Arms/Cams/Contacts / Lock Box/Lock Roller/Restrictor Communication Fault (A1) Adjusted / Repaired  8.0 Minutes (Saurabh Kumar) DC No: K2: A1 Hoistway Lock - Arms/Cams/Contacts / Lock Box/Lock Roller/Restrictor Communication Fault Lift is not working due to 4th floor door contact not connected properly, coor contact	CONFIRM OUT	CONFIRM OUT	CONFIRM

now lift working fine

(CALLER) PROBLEM CUSTOM

CALL

CALL

CALL

reconnect now Duplex working condition ok

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers Or EC - Only VFM Receive				_	ble, No	OF - N	lo
1186895	09:03		(rahul) S1605 and S16096 both lift there is no connectivity both lift connectivity has to be done	-S16095) -						
29/04/25	29/04/25 09:21	1 29/04/25 10:1	5 (C8) Power Supply / Transformer / Rectifie	,						
INV109143	29/04/25 09:23	3	(KA) Component Tripped (A7) Reset and Tested	i						
6396631489 6396631489		20.0 Minutes	(Rajkumar Singh) C8: KA: A7 Power Supply / Transformer / Rectified Component Tripped  Power supply failure from client side. Main drive in controller tripped. checked supply and reset drive and controller. Lift is working now.							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	ıble, N	OF - N	lo	
Lift No. All > 1	29 GR					STP MAX	SWP SWPOA			REC REJ	
1185464	14:47		(Rahul) 6396631489 Lift not working.	128 GR (2-13 -S16095) - Elevator> MR>Gear ed		<u> </u>					
24/04/25	24/04/25 14:58	3 24/04/25 16:5	2 (CX) Controller-Other								
INDIA440697	7 24/04/25 14:59	)	(K2) Communication Fault (AX) Action - Other								
6396631489, 8920799565	2.1 Hours	12.0 Minutes	(Sohan Veer Singh) CX: K2: AX Controller-Other Communication Fault  Error NA Some time cop call book but lift not running Dcl card problem Dcl card change lift working now	Yes							

CALL

			(CALLER) PROBLEM	ER UNIT						
DATE	CONFIRM	оит	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers Or EC - Only VFM Receive				-	ble, N	OF - N	No
1187119	16:11		(Rahul) Lift not working door issue lift stuck on fourth floor door unable to close	129 GR (2-13 -S16096) - Elevator> MR>Gear ed						]
29/04/25	29/04/25 16:5	55 29/04/25 18:3	5 (DX) Door - Other							]
INDIA4420856	6 29/04/25 18:2	29	(K2) Communication Fault (AX) Action - Other							
6396631489, 8920799565		2.3 Hours	(Raja .) DX : K2 : AX Door - Other Communication Fault	No						
			Lift was not working Error- N/A Action- car door adjust and sensor wiring check now lift working condition ok							
Lift No. All > 1	3 GR					STP MAX	SWP SWPOA			REC REJ
1179590	11:40		(Mohan) Button issue	13 GR (2-13 -S16016) - Elevator> MR>Gear ed						]
06/04/25	06/04/25 11:5	58 06/04/25 12:4	7 (SX) Shaft - Other							
INDIA4361138	5 06/04/25 12:3	35	(K2) Communication Fault (A1) Adjusted / Repaired							
9599344130, 9599344130		55.0 Minutes	(Raja .) SX : K2 : A1 Shaft - Other Communication Fault	No						
			Lift working condition Cop 2floor button rewiring now button working condition ok							

CALL

OALL	LOGGLD		(CALLER) I ROBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA	A/H CHG		RI	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	I							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	ıble, N	OF - 1	No	
1186486	19:34		(Navin ) Lift not working.	13 GR (2-13 -S16016) - Elevator> MR>Gear ed		_ Ø		_	_	<u>d</u> -1	
27/04/25	27/04/25 21:3	32 27/04/25 22:1	1 (EX) Lift Car - Other					$\overline{\mathscr{C}}$		]_	
INDIA441503	5 27/04/25 21:3	34	(KZ) Running at Arrival and No Fault Found (AX) Action - Other								
9871537634, 9871537634	2.6 Hours	2.0 Hours	(Hovendra Kumar) EX: KZ: AX Lift Car - Other Running at Arrival and No Fault Found  Lift running on arrival when i reached on site 15 minutes check on lift running no issues in lift	No							

CALL

CALL	LOGGED		(CALLER) PROBLEM	I CUSTOM ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers On EC - Only VFM Receive				-	ıble, N	OF - 1	No	
Lift No. All >	136. GR					STP MAX	SWP SWPOA			REC REJ	
1178020	14:20		(Ravindra) DISPLAY NOT WORKING	136. GR (2-13 -S16099) - Elevator> MR>Gear ed						]	
01/04/25	01/04/25 15:	36 01/04/25 15:5	66 (S8) Landing Arrival & Position -Fixture/Display/Gong /Indication/PCB					_ Ø		]	
INDIA434918	80 01/04/25 15:	36	(K6) Component Missing (AX) Action - Other								
7500487040, 7500487040		1.3 Hours	(Hovendra Kumar) S8: K6: AX Landing Arrival & Position -Fixture/Display/Gong /Indication/PCB Component Missing  LOP not working due to 1 floor lop missing and 3F,4F floor lop damage so need to	No							

be change, arrange

shortly

CALL

CALL

CALL	LOGGED		(CALLER) PROBLEM	I CUSTOM ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	lo	
Lift No. All > 1	37. GR					STP MAX	SWP SWPOA			REC REJ	
1178286	11:54		(Ravindra ) fan issue								
02/04/25	02/04/25 12:	00							₹		
									Cust omer canc el ca	·	
7500487040, 7500487040	0		(Sanjay Verma) : :	No							
1187120	16:12		(Prashan Kumar) Door issue	137. GR (2-13 -S16100) - Elevator> MR>Gear ed						I <sup>-</sup>	
29/04/25	29/04/25 16:	55 29/04/25 18:2	8 (SX) Shaft - Other					_		l	
INDIA442082	9 29/04/25 16:	55	(K2) Communication Fault (AX) Action - Other								
9971980340, 8920799565		43.0 Minutes	(Raja .) SX : K2 : AX Shaft - Other Communication Fault								
			Lift was not working Error- N/A								

Action- Door drive need to check required

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, No	OF - N	No	
Lift No. All > 1	38. GR					STP MAX	SWP SWPOA			REC REJ	
1180145	07:26		(dilsad) display not working	138. GR (2-13 -S16101) - Elevator> MR>Gear ed						] Ø	
08/04/25	08/04/25 07:3	9 08/04/25 08:1	8 (SX) Shaft - Other							]	
INDIA436453	3 08/04/25 08:0	93	(K2) Communication Fault (AX) Action - Other								
8273075959		37.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault 6th floor lop display worong show display resave display	No							

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA	-	_	REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
			uck With Passengers O EC - Only VFM Receive					able, N	OF - N	lo
1184948	07:10		(dilshad ) display not working on 6th floor	138. GR (2-13 -S16101) - Elevator> MR>Gear ed				_		I <sup>−</sup> ⊠
23/04/25	23/04/25 07:	24 23/04/25 07:5	6 (E1) C.O.P Buttons/Keyswitches/ Indicators/Display/P CB							
INDIA440196	3 23/04/25 07:	24	(K2) Communication Fault (A1) Adjusted / Repaired							
8273075959, 8273075959		14.0 Minutes	(Hovendra Kumar) E1: K2: A1 C.O.P Buttons/Keyswitches/ Indicators/Display/P CB Communication Fault Lift was working but 6th floor lop display was not working, Now check display found shaft ware problem, now check display shortware and check wiring reconnect now display							

working condition

(CALLER) PROBLEM CUSTOM

CALL

CALL	LOGGED		(CALLER) PROBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	lo	
Lift No. All > 1	39. GR					STP MAX	SWP SWPOA		NOF CC	REC REJ	
1182685	07:23		(Dilshad) lift light not working					$\overline{\mathscr{C}}$			
16/04/25									₹		
									Cust omer canc el ca		
8273075959, 8273075959	0		(Sanjay Verma) : :	No							
Lift No. All > 1	4 GR					STP MAX	SWP SWPOA			REC REJ	
1180188	09:33		(ram) not working properly	14 GR (2-13 -S16017) - Elevator> MR>Gear ed						I <sup>-</sup>	
08/04/25	08/04/25 10:	08 08/04/25 10:5	5 (SX) Shaft - Other					$\overline{\mathbf{Z}}$			
INDIA436470	2 08/04/25 10:	10	(K2) Communication Fault (AX) Action - Other								
8376936563, 8920799565		37.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault								
			Elevator running on								

arrival

(CALLER) PROBLEM CUSTOM

CALL

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, No	OF - N	lo	
Lift No. All > 1	41. GR					STP MAX	SWP SWPOA			REC REJ	
1177826	07:25		(Rajendra) Lift not working	152 GR (2-13 -S16127) - Elevator> MR>Gear ed		<u> </u>					
01/04/25	01/04/25 07:3	8 01/04/25 08:1	5 (SX) Shaft - Other								
INDIA434800	6 01/04/25 07:4	1	(K2) Communication Fault (AX) Action - Other								
8474912168, 8474912168	50.0 Minutes	16.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault Elevator stop at ground floor permanent open command dol wire problem need to be clear Elevator shutdown	No							

CALL

			,	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC		
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	lo	
Lift No. All > 1	43 GR					STP MAX	SWP SWPOA		NOF CC	REC REJ	
1180537	10:02		(Mukesh) Lift not working	143 GR (2-13 -S16118) - Elevator> MR>Gear ed		<u> </u>					
09/04/25	09/04/25 10:	45 09/04/25 12:0	8 (P7) Drive Protection -Fuse/Circuit Breaker/Thermal Switch								
INDIA436754	0 09/04/25 10:	51	(KA) Component Tripped (A9) Switched Off for Repairs								
6397166345, 8920799565	2.1 Hours	49.0 Minutes	(Hovendra Kumar) P7: KA: A9 Drive Protection -Fuse/Circuit Breaker/Thermal Switch Component Tripped	No							
			Lift was not working Fault. Error 13 break switch Action. Break switch gap adjust and Error reset now elevator working ok								

CALL

9910833036

CALL	LOGGED		(CALLER) PROBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	ble, N	OF - N	Ю	
Lift No. All > 1	45 GR					STP MAX	SWP SWPOA			REC REJ	
1179432	17:44		(Chattu Kumar ) lift not working.	145 GR (2-13 -S16120) - Elevator> MR>Gear ed		<u> </u>				]_[6]	
05/04/25	05/04/25 19:4	16 05/04/25 20:1	5 (D6) Door Panel								
INDIA436075	7 05/04/25 20:0	)4	(K4) Component Damaged / Broken / Stripped (A9) Switched Off for Repairs								
9910833036, 9910833036	2.5 Hours	2.3 Hours	(Aasif.) D6: K4: A9 Door Panel Component Damaged / Broken / Stripped  Lift was not working, due to some one Damaged and Car door track rollers Damaged, sensor Damaged, balance plate Damaged, skate Damaged, RH sides., Lift under shutdown to								

CALL

CALL	LOGGED		(CALLER) PROBLEM	CUSTOM ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	I							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		ick With Passengers Or EC - Only VFM Receive				_	ıble, N	OF - N	lo .	
1180062	18:32		(Brigadier Navjot Singh ) lift not working and door issue multiple times, jerking issue.	-S16120) -				_ _	i <sup>-</sup> ⊏	] 🗹	
07/04/25	07/04/25 18:5	3 07/04/25 19:11	(SX) Shaft - Other							]	
INDIA4364247	7 07/04/25 18:5	55	(K2) Communication Fault (AX) Action - Other								
9968656672, 9968656672	39.0 Minutes	23.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault	No							
			Elevator stop at 1st floor landing door contact problem contact clean and adjust elevator working fine								
1180099	21:08		(Samshad) Not working					_	( <sup>-</sup> _	]	
07/04/25									_ 	j	
									Cust ome canc el ca	r :	
6398433490, 6398433490	0		(Raja .) ::	No							

CALL

CALL	LOGGED		(CALLER) PROBLEM	CUSTOM ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC		
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
			uck With Passengers Or EC - Only VFM Receive					able, N	OF - N	lo	
1187357	13:21		(navjot) not working.	145 GR (2-13 -S16120) - Elevator> MR>Gear ed					_	_⊠_	
30/04/25	30/04/25 13:	38 30/04/25 15:1	6 (EX) Lift Car - Other					✓			
INDIA4422853	3 30/04/25 14:	07	(KZ) Running at Arrival and No Fault Found (AX) Action - Other								
9968656672, 9968656672		46.0 Minutes	(Raja .) EX : KZ : AX Lift Car - Other Running at Arrival and No Fault Found								
			Lift was working condition ok I have check and found lift running on arrival no fault found lift check 30 minutes								
1187358	13:24		(ramdev) door is not opening								
30/04/25									_ <b>∀</b>		
									Cust omer canc el cal		
9651880581, 9651880581	0		(Raja .) ::	No							

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	•		uck With Passengers Or EC - Only VFM Receive				•	ible, N	OF - N	10	
Lift No. All > 1	46 GR					STP MAX	SWP SWPOA			REC REJ	
1177940	11:12		(ravindar ) noise issue while running	e 137. GR (2-13 -S16100) - Elevator> MR>Gear ed						]_6	
01/04/25	01/04/25 11:1	18 01/04/25 12:5	5 (CX) Controller-Other								
INDIA434844	2 01/04/25 11:5	55	(K2) Communication Fault (AX) Action - Other								
7500487040, 7500487040		43.0 Minutes	(Sanjay Verma) CX: K2: AX Controller-Other Communication Fault Elevator running time noise Break adjust and 5th floor landing door roller adjust noise removed	No							

CALL

· · · · · ·			(0/12221)	ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	•		uck With Passengers O				-	able, N	OF - N	lo
1179837	09:46		(App) 4Q lift 144. Lifts/Lift Functioning including Fans lights and all its issues • 4Q-1301 IN PROGRESS 05 Apr · Request ID 167493 Lift 144 non functional on 13th floor. Gives service only till 12th floor add_commentRaised by Colonel Vinod Gupta · Community Level	144 GR (2-13 -S16119) - Elevator> MR>Gear ed						1 ☑
07/04/25	07/04/25 09:	57 07/04/25 10:5	55 (EX) Lift Car - Other							I <sup>-</sup>
INDIA436201	19 07/04/25 10:0	00	(K2) Communication Fault (A7) Reset and Tested	İ						
8447091893		14.0 Minutes	(Sohan Veer Singh) EX: K2: A7 Lift Car - Other Communication Fault	No						
			Some time door problem Door drive Parameter adjust							

LOGGED

CALL

CALL	LOGGED		(CALLER) FROBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	ıble, N	OF - N	lo	
1181671	17:25		(Akash Kumar) Not working	146 GR (2-13 -S16121) - Elevator> MR>Gear ed				_ 	í <sup>-</sup> □	-⊠-	
12/04/25	12/04/25 20:0	8 12/04/25 20:1	0 (C2) Circuit Protection-Circuit Breaker/Fuse/RCD/O verload						<sup>_</sup> _	I <sup>-</sup> -	
INDIA4377836	5 12/04/25 20:00	8	(K2) Communication Fault (A1) Adjusted / Repaired								
8860487374, 8860487374	2.8 Hours	2.7 Hours	(Raja .) C2 : K2 : A1 Circuit Protection-Circuit Breaker/Fuse/RCD/O verload Communication Fault Error 12 Permanent	No							
			Error clear and break switch adjust now lift working condition								

Shutdown clear

(CALLER) PROBLEM CUSTOM

CALL

			,	ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	No
1185518	17:32		(Chatu Kumar) Lift now	t 145 GR (2-13 -S16120) - Elevator> MR>Gear ed				_	·⊏	]_8
24/04/25	24/04/25 17:	39 24/04/25 18:3	86 (EX) Lift Car - Other							]
INDIA440773	33 24/04/25 17:	40	(K2) Communication Fault (AX) Action - Other							
9910833036		8.0 Minutes	(Sohan Veer Singh) EX: K2: AX Lift Car - Other Communication Fault Lift shutdown problem not solved I am working here	No						

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	I						
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
			uck With Passengers Or EC - Only VFM Receive					able, N	OF - N	lo
Lift No. All > 1	47 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ
1180343	15:19		(Akash Kumar) Lift not working	147 GR (2-13 -S16122) - Elevator> MR>Gear ed						
08/04/25	08/04/25 16:	19 08/04/25 16:5	7 (D4) Door Closer -Weight/Rope/Spirator /Spring/Arm							
INDIA436604	0 08/04/25 16:	19	(K4) Component Damaged / Broken / Stripped (A1) Adjusted / Repaired							
8630369181, 8630369181	1.6 Hours	1.0 Hour	(Aasif .) D4 : K4 : A1 Door Closer -Weight/Rope/Spirator /Spring/Arm Component Damaged / Broken / Stripped							
			Lift was not working, due to 3rd floor landing Door spring damaged. Now spring repair now lift working condition ok							

CALL

			ER UNIT							
CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
IN	SWP REL		I							
TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
							ble, No	OF - N	0	
12:47		(Dipak Arora) Both lift not working from same tower	147 GR (2-13 -S16122) - Elevator> MR>Gear ed						_ [2]	
09/04/25 13:0	09 09/04/25 14:3	3 (T1) Brake -Drum/Shoe/Coil/Link ages/Spring/Switch								
4 09/04/25 13:3	34	(K7) Component or Connection - Loose (A1) Adjusted / Repaired								
1.8 Hours	47.0 Minutes	ages/Spring/Switch Component or Connection - Loose Lift was not working	No							
	TIME STOPPED  With Passenge III cancelled, Side 12:47  09/04/25 13:04	TIME RESPONSE STOPPED TIME  With Passengers, SWPOA - Stull cancelled, STP - Stopped, R  12:47  09/04/25 13:09 09/04/25 14:3	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) ACTION  With Passengers, SWPOA - Stuck With Passengers Or all cancelled, STP - Stopped, REC - Only VFM Received  12:47 (Dipak Arora) Both lift not working from same tower  09/04/25 13:09 09/04/25 14:33 (T1) Brake -Drum/Shoe/Coil/Link ages/Spring/Switch  (K7) Component or Connection - Loose (A1) Adjusted / Repaired  1.8 Hours 47.0 Minutes (Hovendra Kumar) T1 : K7 : A1 Brake -Drum/Shoe/Coil/Link ages/Spring/Switch Component or Connection - Loose Lift was not working Fault. Error 13 coming break switch Action. Break switch	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) STOPPED TIME ACTION MATERIA L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H Ill cancelled, STP - Stopped, REC - Only VFM Received Calls, RE.  12:47 (Dipak Arora) Both lift not working from same tower Sa	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hou III cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ -	IN SWP REL (No.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG III cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Reject  12:47 (Dipak Arora) Both lift 147 GR not working from (2-13 same tower S16122) - Elevator> MR>Gear ed  09/04/25 13:09 09/04/25 14:33 (T1)  Brake -Drum/Shoe/Coil/Link ages/Spring/Switch  1.8 Hours 47.0 Minutes (Hovendra Kumar) No T1: KT: A1 Brake -Drum/Shoe/Coil/Link ages/Spring/Switch Component or Connection - Loose (A1) Adjusted / Repaired  1.8 Hours 47.0 Minutes (Hovendra Kumar) No T1: KT: A1 Brake -Drum/Shoe/Coil/Link ages/Spring/Switch Component or Connection - Loose Lift was not working Fault. Error 13 coming break switch Action. Break switch gep adjust and error	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargea Ill cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  12:47 (Dipak Arora) Both lift 147 GR not working from (2-13 same tower S16122) - Elevator> MR>Gear ed  09/04/25 13:09 09/04/25 14:33 (T1) Brake -Drum/Shoe/Coil/Link ages/Spring/Switch  1.8 Hours 47.0 Minutes (Hovendra Kumar) T1 : K7 : A1 Brake -Drum/Shoe/Coil/Link ages/Spring/Switch Component or Connection - Loose (A1) Adjusted / Repaired  1.8 Hours 47.0 Minutes (Hovendra Kumar) T1 : K7 : A1 Brake -Drum/Shoe/Coil/Link ages/Spring/Switch Component or Connection - Loose Lift was not working Fault. Error 13 coming break switch gep adjust and error	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA GE LUSED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Charge-able, No. III cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  12:47 (Dipak Arora) Both lift 147 GR not working from (2-13 same tower S16122) - Elevator> MR>Gear ed  09/04/25 13:39 09/04/25 14:33 (T1) Brake - Drum/Shoe/Coil/Link ages/Spring/Switch  109/04/25 13:34 (K7) Component or Connection - Loose (A1) Adjusted / Repaired  1.8 Hours 47.0 Minutes (Hovendra Kumar) No T1 : K7 : A1 Brake - Drum/Shoe/Coil/Link ages/Spring/Switch Component or Connection - Loose Lift was not working Fault. Error 13 coming break switch Action. Breaks witch Action. Breaks witch gep adjust and error	CONFIRM OUT (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - N III cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  12:47 (Dipak Arora) Both lift 147 GR not working from (2-13 same tower S16122) - Elevators- MR>Gear ed  09/04/25 13:09 09/04/25 14:33 (T1)  Brake - Drum/Shoe/Coil/Link ages/Spring/Switch  1.8 Hours 47.0 Minutes (Hovendra Kumar) Repaired  1.8 Hours 47.0 Minutes (Hovendra Kumar) Repaired  1.8 Hours 47.0 Minutes (Hovendra Kumar) Repaired  Lift was not working Fault. Error 13 coming break switch gep adjust and error	No.   SWP REL   (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION   SWP REL (NO.) FAULT ACTION   STOPPED   TIME   RESPONSE (NO.) FAULT ACTION   STOPPED   REC (NO.) FAULT ACTION   SWP REL (NO.) F

working now

(CALLER) PROBLEM CUSTOM

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NO G CC		REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	•		uck With Passengers O EC - Only VFM Receive				-	able, N	IOF -	No	
1187294	10:11		(AKASH) NOT WORKING	147 GR (2-13 -S16122) - Elevator> MR>Gear ed					]_[	<u> </u>	☑
30/04/25	30/04/25 10:4	4730/04/25 11:3	2 (C3) Contactor/Relay/Time	r					]_[		
INDIA442170	08 30/04/25 11:0	01	(K2) Communication Fault (AX) Action - Other								
8860487374 8920799565		50.0 Minutes	(Raja .) C3 : K2 : AX Contactor/Relay/Time Communication Fault	r							
			Lift was not working Error- N/A Action Controller wiring need to check required								

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O				-	ıble, N	OF - N	lo	
Lift No. All > '	148 GR					STP MAX	SWP SWPOA			REC REJ	
1178440	19:48		(Rakesh Arora ) fan and light not working.	148 GR (2-13 -S16123) - Elevator> MR>Gear ed				_ Ø			
02/04/25	02/04/25 20::	24 02/04/25 21:0	9 (E8) Lighting / Ventilation								
INDIA435308	30 02/04/25 20::	24	(KW) User Error or Customer Request (A5) No Action Taken / No Access Possible, Customer To Be Notified								
9560193247, 9560193247		36.0 Minutes	(Aasif .) E8 : KW : A5 Lighting / Ventilation User Error or Customer Request	No							
			Lift is working fine, only car fan not working need to be change information to customer RWA, fan required by customer	)							

CALL

CALL

CALL

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	ble, N	OF - N	lo	
Lift No. All > 1	52 GR					STP MAX	SWP SWPOA			REC REJ	
1181533	10:40		(Mob app) 4U lift 152 Cardoor problem, automatically hold.	, 152 GR (2-13 -S16127) - Elevator> MR>Gear ed		<u> </u>					
12/04/25	12/04/25 11:2	3 12/04/25 13:2	3 (D5) Door Operator - Motor / Gear Box / Belt / Chain / Static Drive								
INDIA4376110	) 12/04/25 11:2	3	(K2) Communication Fault (A6) Replaced Component								
8447091893, 8920799565	2.7 Hours	43.0 Minutes	(Hovendra Kumar) D5: K2: A6 Door Operator - Motor / Gear Box / Belt / Chain / Static Drive Communication Fault Lift was working but some time door Stop for level now new dol dcl switch replace now elevator working	Yes							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	lo	
Lift No. All >	153 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1181560	11:22		(amit) er error	153 GR (2-13 -S16128) - Elevator> MR>Gear ed						I¯Ø¯	
12/04/25	12/04/25 12:	27 12/04/25 14:3	st (DG) Switch/Microswitch/P roximity/Limit Switch/Bi-stable								
INDIA437640	08 12/04/25 13:	23	(K7) Component or Connection - Loose (A1) Adjusted / Repaired								
8178744489 8920799565	,	2.0 Hours	(Hovendra Kumar) DG: K7: A1 Switch/Microswitch/P roximity/Limit Switch/Bi-stable Component or Connection - Loose	No							
			Lift was working Fault. Some time doo not open Action. Red switch wairing reconnect and up dn final slowing switch clean now elevator working ok								

CALL

CALL

			(OALLEN) I NOBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	-		uck With Passengers Oi EC - Only VFM Receive				-	able, NO	OF - N	lo	
Lift No. All > 1	158 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1181748	08:08		(Navjot ) Panel button not work	144 GR (2-13 -S16119) - Elevator> MR>Gear ed				_ ⊠			
13/04/25	13/04/25 09:	13 13/04/25 10:5	2(E1) C.O.P Buttons/Keyswitches/ Indicators/Display/P CB							ı <sup>-</sup>	
INDIA437808	6 13/04/25 10:-	48	(K4) Component Damaged / Broken / Stripped (A5) No Action Taken / No Access Possible, Customer To Be Notified								
9968656672, 9968656672		2.7 Hours	(Aasif ., Rajkumar Singh) E1 : K4 : A5 C.O.P Buttons/Keyswitches/ Indicators/Display/P CB Component Damaged / Broken / Stripped Lift working but 10th floor cop button Cover not available Action:- 10th floor cop new required lift								

working condition ok

(CALLER) PROBLEM CUSTOM

CALL

OALL	LOGOLD		(OALLEN) MOBILIN	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	I							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers On EC - Only VFM Receive				_	able, No	OF - N	lo	
Lift No. All > 1	6 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1178327	13:32		(Mobile App) 1F lift 16 Lift 16 doors jutter/vibrate while opening and closing.	. 16 GR (2-13 -S16019) - Elevator> MR>Gear ed							
02/04/25	02/04/25 14:	12 02/04/25 14:1	4 (DB) Hanger Assembly -Roller/Upthrust/Track /Bracket/Header								
INDIA435147	3 02/04/25 14:	12	(K4) Component Damaged / Broken / Stripped (A6) Replaced Component								
8447091893, 8447091893		40.0 Minutes	(Aasif .) DB : K4 : A6 Hanger Assembly -Roller/Upthrust/Track /Bracket/Header Component Damaged / Broken / Stripped								
			Car door running time vibration, now car door rollar changed and door is open and close working fine								
Lift No. All > 1	60 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	

CALL

1179839	09:47		(App) 4Y lift 160, 161 Lifts/Lift Functioning including Fans lights and all its issues • 4Y-501 IN PROGRESS 11:05 AM · Request ID 167615 Lift Nos 160 and 161 (4Y)do not have the number of the lifts nor numbers of the service providers, it should have both and also dos and don'ts One of the lift doors also does not shut in one go, it opens and then once close button is pressed second time it closes add_commentRaised by Brig Gautam Oberoi · Unit Level	(2-13 -S16135) - Elevator> MR>Gearl			$\mathbf{Y}$	
07/04/25	07/04/25 10:05	07/04/25 11:41	(D2) Door Controller - PCB / Processor/Door encoder					
INDIA4362186	07/04/25 10:56	i	(K2) Communication Fault (A1) Adjusted / Repaired					
8447091893		1.2 Hours	(Aasif., Sohan Veer Singh) D2: K2: A1 Door Controller - PCB / Processor/Door encoder Communication Fault Block 4y161, Check lift condition Door not closed one time and DOB problem on Sensor was dusty Now Door v3f Parameter adjust and Sensor clean now lift working condition ok  Note:- Ther is no any sticker of DO& Don't plate required, In lift no 160& 161, Safty warning plate missing Required DCB button is wrong required,  4y, L.no. 160 Check lift condition no any Door escape lift working ok condition.	No				

LOGGLD		(CALLER) I ROBLEM	ER UNIT							
CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA				EC EJ
IN	SWP REL									
TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
_		-				_	able, N	OF -	No	
09:14		(App) 4Y lift 160 not working.	160 GR (2-13 -S16135) - Elevator> MR>Gearl ess					I <sup>-</sup> C		
29/04/25 10:	1429/04/25 12:1	9 (DX) Door - Other						_[	]	
94 29/04/25 10:	33	(K2) Communication Fault (A1) Adjusted / Repaired								
	1.3 Hours	(Rajkumar Singh) DX : K2 : A1 Door - Other Communication Fault Lift was not working Error- N/A Action- 5th floor landing door adjust now lift working condition ok								
	CONFIRM  IN  TIME STOPPED  With Passenge all cancelled, S  09:14	CONFIRM OUT  IN SWP REL  TIME RESPONSE STOPPED TIME  With Passengers, SWPOA - St all cancelled, STP - Stopped, R  09:14  29/04/25 10:1429/04/25 12:1	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) STOPPED TIME ACTION  With Passengers, SWPOA - Stuck With Passengers O all cancelled, STP - Stopped, REC - Only VFM Received  09:14 (App) 4Y lift 160 not working.  29/04/25 10:14 29/04/25 12:19 (DX) Door - Other working.  (K2) Communication Fault (A1) Adjusted / Repaired  1.3 Hours (Rajkumar Singh) DX : K2 : A1 Door - Other Communication Fault Lift was not working Error- N/A Action- 5th floor landing door adjust now lift working	CONFIRM OUT (NO.) FAULT  IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS MATERIA L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/rall cancelled, STP - Stopped, REC - Only VFM Received Calls, RE  09:14 (App) 4Y lift 160 not working. (2-13 - S16135) - Elevator> MR>Gearl ess  29/04/25 10:14 29/04/25 12:19 (DX) Door - Other  14 29/04/25 10:33 (K2) Communication Fault (A1) Adjusted / Repaired  1.3 Hours (Rajkumar Singh) DX No: K2: A1 Door - Other Communication Fault  Lift was not working Error- N/A Action- 5th floor landing door adjust now lift working	CONFIRM OUT	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Reject working.  (App) 4Y lift 160 not 160 GR working. (2-13 - S16135) - Elevator> MR>Gearl ess  29/04/25 10:14 29/04/25 12:19 (DX) Door - Other  (K2) Communication Fault (A1) Adjusted / Repaired  1.3 Hours (Rajkumar Singh) DX No : K2 : A1 Door - Other Communication Fault Lift was not working Error- N/A Action - 5th floor landing door adjust now lift working	CONFIRM OUT (NO.) FAULT STP SWP MAX SWPOA  IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Charged all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  O9:14 (App) 4Y lift 160 not 160 GR working. (2-13 - S16135) - Elevator> MR>Gearl ess  29/04/25 10:14 29/04/25 12:19 (DX) Door - Other Sult (A1) Adjusted / Repaired  1.3 Hours (Rajkumar Singh) DX No: K2: A1 Door - Other Communication Fault Lift was not working Error- N/A Action- 5th floor landing door adjust now lift working	CONFIRM OUT (NO.) FAULT STP SWP A/H MAX SWPOA CHG  IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA ACTION MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, N all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  09:14 (App) 4Y lift 160 not 160 GR working. (2-13 - S16135) - Elevators MR>Gearl ess  29/04/25 10:14 29/04/25 12:19 (DX) Door - Other MR>Gearl ess  1.3 Hours (Rajkumar Singh) DX No: K2: A1 Door - Other Communication Fault Lift was not working Error- NIA Action- 5th floor landing door adjust now lift working	CONFIRM OUT	CONFIRM OUT

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	RE RE	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	able, No	OF - N	No	
Lift No. All > 1	162 GR					STP MAX	SWP SWPOA	A/H CHG		RE RE	
1181580	12:29		(rahul ) door issue	162 GR (2-13 -S15975) - Elevator> MR>Gear ed					_ &	) <u> </u>	ZÍ
12/04/25	12/04/25 13:0	03 12/04/25 13:4	9 (DX) Door - Other					_		]_[	
INDIA437622	5 12/04/25 13:0	03	(KZ) Running at Arrival and No Fault Found (AX) Action - Other								
9675289535, 9675289535		34.0 Minutes	(Sohan Veer Singh) DX: KZ: AX Door - Other Running at Arrival and No Fault Found  Running time door sound Door roller to be replace	Yes							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	able, No	OF - N	lo	
Lift No. All > 1	17 GR					STP MAX	SWP SWPOA			REC REJ	
1178331	13:36		(mobile app) 1F lift 17 Leveling problem on the Ground floor.	. 17 GR (2-13 -S16020) - Elevator> MR>Gear ed					_ ₩		
02/04/25	02/04/25 14:	1202/04/25 14:4	2 (EX) Lift Car - Other					$\overline{\mathscr{C}}$			
INDIA435161	0 02/04/25 14:′	15	(KZ) Running at Arrival and No Fault Found (AA) Tested Operation / No Fault Found								
8447091893, 8920799565		39.0 Minutes	(Aasif .) EX : KZ : AA Lift Car - Other Running at Arrival and No Fault Found								
			Lift running on arrival, and we are checked many time of ground floor leveling but no issue found and lift is working fine								

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPO#		NO G CC		REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	•		uck With Passengers Or EC - Only VFM Receive				-	able, N	IOF -	No	)
1179286	11:24		(Mobile App) 1F lift 17 some one stuck.	17 GR (2-13 -S16020) - Elevator> MR>Gear ed					]_[	<u></u>	<u> </u>
05/04/25	05/04/25 11:4	40 05/04/25 12:5	3 (EX) Lift Car - Other						]_[		
INDIA435926	65 05/04/25 11:4	48	(KB) Component Worr (AX) Action - Other	n							
8447091893, 8447091893		24.0 Minutes	(Rajkumar Singh) EX: KB: AX Lift Car - Other Component Worn  Lift working but running times jurk from 7th to 8th floor, Need to be check properly. Lift under follow up fir checking	No							

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	•		uck With Passengers Or EC - Only VFM Receive				-	ible, N	OF - N	lo
1183784	12:27		(Mobile app) 1F lift 17 Someone stuck inside the lift. Rescue completed within 10 minutes.			_				
19/04/25	19/04/25 12:5	55 19/04/25 15:1	3 (PX) Drive - Other							
INDIA4393745	5 19/04/25 12:5	56	(KA) Component Tripped (A7) Reset and Tested	i						
8447091893, 8447091893	2.8 Hours	29.0 Minutes	(Sohan Veer Singh) PX: KA: A7 Drive - Other Component Tripped  Drive trip Error oc2 Mc mc1 contactor all wire reconnect and no point check Some time lift stop without lavel Reed switch wire check and re contact	No						

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - 1	No	
1185653	09:14		(Mobile app) 1F lift 17 floors level out.	17 GR (2-13 -S16020) - Elevator> MR>Gear ed						]	
25/04/25	25/04/25 09:3	33 25/04/25 10:5	3 (SX) Shaft - Other							]	
INDIA440835	8 25/04/25 10:2	20	(K2) Communication Fault (AX) Action - Other								
8447091893, 8447091893		1.1 Hours	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault Elevator not working stop at ground floor								
			leval out hwc pcb problem pcb replace elevator working								

CALL

(Saurabh Kumar) : : No

9849252790, 0

9849252790

CALL

CALL

OALL	LOGGLD		(OALLEN) I NOBELIN	ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O REC - Only VFM Receive				_	able, N	OF - N	lo
1179419	17:17		(Vinay Goel ) lift not working.	22 GR (2-13 -S16025) - Elevator> MR>Gear ed				_	i <sup>-</sup> □	_ <u>&amp;</u> _
05/04/25	05/04/25 19:	46 05/04/25 19:5	59 (EX) Lift Car - Other							
INDIA436074	4 05/04/25 19:	55	(K4) Component Damaged / Broken / Stripped (A9) Switched Off for Repairs							
9910040714, 9910040714	2.7 Hours	2.6 Hours	(Aasif .) EX : K4 : A9 Lift Car - Other Component Damaged / Broken / Stripped							
			Lift is already not working, shut dueto traveling cable work ir progress.	า						
1183867	16:59		(Vivek) Jerk							- <del>-</del>
19/04/25										
									Cust omer canc el ca	
9335599749, 9335599749	0		(Raja .) ::	No						

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O EC - Only VFM Receive				_	ıble, N	OF - N	do .
1185570	20:44		(Digambar ) Lift not working and jerking.	22 GR (2-13 -S16025) - Elevator> MR>Gear ed		 Ø		_		]_6
24/04/25	24/04/25 20:5	51 24/04/25 21:1	7 (EX) Lift Car - Other							I <sup>-</sup>
INDIA440798	4 24/04/25 20:5	53	(K2) Communication Fault (AX) Action - Other							
9625411247, 9625411247	33.0 Minutes	9.0 Minutes	(Saurabh Kumar) EX: K2: AX Lift Car - Other Communication Fault Lift Sometime not moving, some communication problem so need to be check and we are working here, so lift is shutdown for fault checking, lift operational after							

sometime

(CALLER) PROBLEM CUSTOM

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	I							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	able, NO	OF - N	lo	
Lift No. All > 2	23 GR					STP MAX	SWP SWPOA			REC REJ	
1179521	08:33		(Vivek) Lift not working	g23 GR (2-13 -S16026) - Elevator> MR>Gear ed		<u> </u>		_ 			
06/04/25	06/04/25 08:	51 06/04/25 09:0	7 (SB) Overtravel Protection-Limit or Tappet Switches								
INDIA436093	39 06/04/25 08:\$	51	(K2) Communication Fault (A1) Adjusted / Repaired								
9335599749, 9335599749	34.0 Minutes	18.0 Minutes	(Raja .) SB : K2 : A1 Overtravel Protection-Limit or Tappet Switches Communication Fault	No							
			Lift was not working Error- N/A Action- limit switch problem limit switch adjust now lift working								

condition ok

(CALLER) PROBLEM CUSTOM

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
			uck With Passengers O EC - Only VFM Receive					able, N	OF - N	lo
Lift No. All > 2	4 GR					STP MAX	SWP SWPOA	A/H CHG	NOF CC	REC REJ
1185844	16:23		(Mahesh Kumar) Not working	24 GR (2-13 -S16027) - Elevator> MR>Gear ed					_ ₩	
25/04/25	25/04/25 16:2	7 25/04/25 17:2	0 (DB) Hanger Assembly -Roller/Upthrust/Track /Bracket/Header							
INDIA441005	3 25/04/25 16:2	8	(KY) Vandalism or Misuse Causing Damage (AX) Action - Other							
8273323609, 8273323609	57.0 Minutes	5.0 Minutes	(Raja .) DB : KY : AX Hanger Assembly -Roller/Upthrust/Track /Bracket/Header Vandalism or Misuse Causing Damage  Customer miss used of lift so 6th floor landing door out of track amd door rollar found damage, now new rollar change and door alignment done							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	•		uck With Passengers O EC - Only VFM Receive				•	ıble, N	OF - N	lo	
Lift No. All > 2	25 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1181824	11:01		(Sudhir kumar) Stuck issue	26 GR (2-13 -S15976) - Elevator> MR>Gear ed					- ₩	(¯□¯	
13/04/25	13/04/25 11:3	32 13/04/25 11:4	9 (EX) Lift Car - Other								
INDIA437815	1 13/04/25 11:3	34	(KZ) Running at Arrival and No Fault Found (AX) Action - Other								
9871248370, 8920799565		33.0 Minutes	(Saurabh Kumar) EX: KZ: AX Lift Car - Other Running at Arrival and No Fault Found  Lift running on arrival, we are checked lift with running but no issue found, lift is working smoothly, no action taken	I							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	ble, N	OF - N	lo	
Lift No. All > 2	6 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1181371	18:13		(Veer Yadav ) lift not working properly.	35 GR (2-13 -S16036) - Elevator> MR>Gear ed		<u> </u>				T	
11/04/25	11/04/25 18:2	7 11/04/25 19:5°	1 (WX) No Fault Found								
INDIA437504	6 11/04/25 18:2	7	(KZ) Running at Arrival and No Fault Found (AX) Action - Other								
9871248370, 9871248370	1.6 Hours	14.0 Minutes	(Hovendra Kumar) WX: KZ: AX No Fault Found Running at Arrival and No Fault Found  Lift running on arrival no Fault customer complain I am going to 6th floor to g floor lift Stop 4and 2ind floor lift Stop at level is am check lift not stop lift working good condition								

CALL

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	ıble, N	OF - N	lo	
Lift No. All > 2	29 GR					STP MAX	SWP SWPOA			REC REJ	
1179567	10:44		(Mahipal singh) lift not working	29 GR (2-13 -S15977) - Elevator> MR>Gear ed		_ ⊠				l	
06/04/25	06/04/25 10:5	54 06/04/25 11:4	0 (SX) Shaft - Other								
INDIA436105	58 06/04/25 11:	30	(K2) Communication Fault (A1) Adjusted / Repaired								
7455974339, 7455974339	56.0 Minutes	46.0 Minutes	(Raja .) SX : K2 : A1 Shaft - Other Communication Fault Lift was not working	No							
			Error- N/A Action- Ground floor landing door contect adjust now lift working condition ok								

CALL

CALL

CALL	LOGGED		(CALLER) PROBLEM	CUSTOM ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
			uck With Passengers O EC - Only VFM Receive					able, No	OF - N	0	
Lift No. All > 3	34 GR					STP MAX	SWP SWPOA	A/H CHG	NOF CC	REC REJ	
1183708	10:01		(Pramod Kumar) Ligh Not Working	t						Ø	
19/04/25									$\square$		
									Cust omer canc el cal	I	
8954952422, 8954952422	0		(Hovendra Kumar) :	No							
Lift No. All > 3	35 GR					STP MAX	SWP SWPOA	A/H CHG	NOF CC	REC REJ	
1180259	11:05		(Pramod Kumar) Lift sound issue	35 GR (2-13 -S16036) - Elevator> MR>Gear ed							
08/04/25	08/04/25 11:	22 08/04/25 13:0	9 (SX) Shaft - Other								
INDIA436510	9 08/04/25 11:	54	(K2) Communication Fault (AX) Action - Other								
8954952422, 8954952422		49.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault								
			Elevator running with problem 7th and 4th floor sket roller adjust								

noise removed

CALL

CALL	LOGGED		(CALLER) PROBLEM	CUSTOM ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC		
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	ıble, N	OF - N	lo	
Lift No. All > 3	86 GR					STP MAX	SWP SWPOA			REC REJ	
1180299	12:39		(dharamsingh) not working properly								
08/04/25									✓		
									Cust omer canc el cal		
9971732781, 8920799565	0		(Aasif .) ::	No							
Lift No. All > 3	37 GR					STP	SWP SWPOA			REC REJ	
1177973	12:12		(Samarth) not working	22 GR (2-13 -S16025) - Elevator> MR>Gear ed							
01/04/25	01/04/25 17:2	23 01/04/25 18:2	1 (D9) Gate Switch								
INDIA435009	6 01/04/25 18:	18	(K2) Communication Fault (A1) Adjusted / Repaired								
8826682291, 8826682291		6.1 Hours	(Rajkumar Singh) D9 : K2 : A1 Gate Switch Communication Fault Lifts was not working problem 7th floor landing door adjust male contect new replace elevator	No							

working now ok

CALL

ok,

			,	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
			ick With Passengers Or EC - Only VFM Receive					able, N	OF - N	lo	
1181754	08:25		(Rahul) Door issue	39 GR (2-13 -S15981) - Elevator> MR>Gear ed				_	( <sup>-</sup>	I_⊠	
13/04/25	13/04/25 09:		(DX) Door - Other						$\Box$	I <sup>_</sup>	
INDIA437810	3 13/04/25 11:0	JS	(K2) Communication Fault (A1) Adjusted / Repaired								
9675289535, 9675289535		2.6 Hours	(Aasif., Rajkumar Singh) DX: K2: A1 Door - Other Communication Fault Lift working but some time, Sensor was problem, Permanente DOB coming by Sensor now Sensor wiring check but Sensor Lift was not working, Problem:- 3rd floor landing door spring break Damaged, Action:- 3rd floor spring repair now lift working condition ok to be replace Lift under follow up.	No							

CALL

OALL	LOGGLD		(OALLEN) I NOBLEN	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			RE	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	able, N	OF -	No	
1182770	10:13		(Mobile app) 2D lift 39 not working	39 GR (2-13 -S15981) - Elevator> MR>Gear ed					I <sup>-</sup> [	]_6	<u>a</u>
16/04/25	16/04/25 10:2	4 16/04/25 11:2	7 (SX) Shaft - Other							]_[	
INDIA438417 <sup>2</sup>	1 16/04/25 10:2	4	(K2) Communication Fault (AX) Action - Other								
8447091893, 8447091893	1.2 Hours	11.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault Elevator not working car door not close door drive defective new door drive replace elevator	Yes							

CALL

			,	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC		
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	lo	
Lift No. All > 4	GR					STP MAX	SWP SWPOA		NOF CC	REC REJ	
1179685	16:05		(nonihal) door issue .	4 GR (2-13 -S16008) - Elevator> MR>Gear ed							
06/04/25	06/04/25 16:	17 06/04/25 18:3	8 (DC) Hoistway Lock -Arms/Cams/Contacts /Lock Box/Lock Roller/Restrictor								
INDIA436159	6 06/04/25 16:	18	(K4) Component Damaged / Broken / Stripped (A6) Replaced Component								
7830955135, 7830955135		13.0 Minutes	(Aasif .) DC : K4 : A6 Hoistway Lock -Arms/Cams/Contacts /Lock Box/Lock Roller/Restrictor Component Damaged / Broken / Stripped								
			Lift was not working, car door out of tracks, and track rollers Damaged, now track rollers 4nos new replace lift working ok condition. Shutdown clear								

CALL

N  TIME STOPPED	SWP REL  RESPONSE TIME	(NO.) FAULT CAUSE (NO.) FAULT ACTION (TECHNICIAN) ACTION			STP MAX	SWP SWPOA	-	_	REC REJ	
TIME STOPPED	RESPONSE TIME	(NO.) FAULT ACTION (TECHNICIAN)	l							
STOPPED	TIME		IS							
th Passenge	re SWPOA - Sti		MATERIA L USED	LIFTUSA GE						
•		uck With Passengers Or EC - Only VFM Receive				-	ble, N	OF - N	0	
GR					STP MAX	SWP SWPOA			REC REJ	
1:56										
25/04/25 12:1	625/04/25 12:5	9 (SX) Shaft - Other								
25/04/25 12:5	53	(K2) Communication Fault (AX) Action - Other								
	57.0 Minutes	(Sanjay Verma) SX : K2 : AX Shaft - Other Communication Fault	No							
2:	5/04/25 12:1	5/04/25 12:16 25/04/25 12:5 5/04/25 12:53	Counter weight sound in running time.  5/04/25 12:1625/04/25 12:59 (SX) Shaft - Other  5/04/25 12:53 (K2) Communication Fault (AX) Action - Other  57.0 Minutes (Sanjay Verma) SX: K2: AX Shaft - Other	Counter weight sound (2-13 in running timeS15982) - Elevator> MR>Gear ed  5/04/25 12:16 25/04/25 12:59 (SX) Shaft - Other  (K2) Communication Fault (AX) Action - Other  57.0 Minutes (Sanjay Verma) SX : No K2 : AX Shaft - Other	Counter weight sound (2-13 in running timeS15982) - Elevator> MR>Gear ed  5/04/25 12:16 25/04/25 12:59 (SX) Shaft - Other  (K2) Communication Fault (AX) Action - Other  57.0 Minutes (Sanjay Verma) SX : No K2 : AX Shaft - Other	Counter weight sound (2-13 in running timeS15982) - Elevator> MR>Gear ed  5/04/25 12:16 25/04/25 12:59 (SX) Shaft - Other  (K2) Communication Fault (AX) Action - Other  57.0 Minutes (Sanjay Verma) SX : No K2 : AX Shaft - Other	Counter weight sound (2-13 in running timeS15982) - Elevator> MR>Gear ed  5/04/25 12:16 25/04/25 12:59 (SX) Shaft - Other  (K2) Communication Fault (AX) Action - Other  57.0 Minutes (Sanjay Verma) SX : No K2 : AX Shaft - Other	Counter weight sound (2-13 in running timeS15982) - Elevator> MR>Gear ed  5/04/25 12:16 25/04/25 12:59 (SX) Shaft - Other  (K2) Communication Fault (AX) Action - Other  57.0 Minutes (Sanjay Verma) SX : No K2 : AX Shaft - Other	Counter weight sound (2-13 in running timeS15982) - Elevator> MR>Gear ed  5/04/25 12:16 25/04/25 12:59 (SX) Shaft - Other  (K2) Communication Fault (AX) Action - Other  57.0 Minutes (Sanjay Verma) SX : No K2 : AX Shaft - Other	Counter weight sound (2-13 in running timeS15982) - Elevator> MR>Gear ed  5/04/25 12:16 25/04/25 12:59 (SX) Shaft - Other  (K2) Communication Fault (AX) Action - Other  57.0 Minutes (Sanjay Verma) SX : No K2 : AX Shaft - Other

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	ıble, N	OF - N	10	
Lift No. All > 4	11 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1180108	22:17		(Subhash) lift not working.stuck on ground floor.	41 GR (2-13 -S15983) - Elevator> MR>Gear ed				<b>□</b>		I <u>_</u> ⊠	
07/04/25	08/04/25 00:2	29 08/04/25 00:5	3 (S6) Floor PCB								
INDIA436449	5 08/04/25 00:3	36	(K7) Component or Connection - Loose (A1) Adjusted / Repaired								
9457731354, 9457731354		2.3 Hours	(Rajkumar Singh) S6: K7: A1 Floor PCB Component or Connection - Loose  Lift was working problem in opening Closig time door. Sound Action- now car door slippers new Replace and door v3: pramiter adjusted elevator working now ok	r f							

CALL

CALL

(CALLER) PROBLEM CUSTOM CALL **LOGGED ER UNIT** STP A/H NOF REC DATE **CONFIRM** OUT (NO.) FAULT **SWP** MAX SWPOA CHG CC REJ DOCKET IN **SWP REL** (NO.) FAULT CAUSE (NO.) FAULT ACTION CONTACT TIME **RESPONSE** (TECHNICIAN) **LIFTUSA** IS **STOPPED** TIME **ACTION** MATERIA GE L USED SWP - Stuck With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - No Fault, CC - Call cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  $\square$  $\square$ 1186501 20:47 (Ram) Lift not working. 42 GR (2-13)-S15984) -Elevator> MR>Gear ed 27/04/25 27/04/25 21:33 28/04/25 02:13 (D4) Door Closer -Weight/Rope/Spirator /Spring/Arm INDIA4415064 27/04/25 23:39 (K1) Burnt Out (A1) Adjusted / Repaired 8285216555, 5.4 Hours 2.9 Hours (Hovendra Kumar) No 8285216555 D4: K1: A1 Door Closer -Weight/Rope/Spirator /Spring/Arm **Burnt Out** Lift was working Fault. Some time level Action. Cupler tuch with latch roller now roller center gep adjust lift working condition ok Lift No. All > 43 GR STP **SWP** A/H NOF REC SWPOA CHG CC MAX REJ 1178851 09:00 (lokesh) fan not working  $\square$ 04/04/25 Bran ch canc el call 8006046839, 0 (Sanjay Verma) : : No 8006046839

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers Or EC - Only VFM Receive				-	ıble, N	OF - N	lo
1186874	08:10		(MANOJ) DOOR ISSUE	43 GR (2-13 -S15986) - Elevator> MR>Gear ed				_	_	
29/04/25	29/04/25 08:	21 29/04/25 08:5	3 (EX) Lift Car - Other					$\overline{\mathscr{C}}$		I <sup>-</sup>
INDIA441823	34 29/04/25 08::	24	(KZ) Running at Arrival and No Fault Found (AA) Tested Operation / No Fault Found							
8287612646		14.0 Minutes	(Rajkumar Singh) EX : KZ : AA Lift Car - Other Running at Arrival and No Fault Found  Lift running on arrival and door open close smoothly no issues found in lift and door							

CALL

· · ·	200022		(OALLEN) I NOBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA	A/H CHG			
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O				_	able, NC	OF - N	lo	
Lift No. All > 4	5 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1181767	09:03		(rohit) lift got struck in 4th floor	99 GR (2-13 -S16075) - Elevator> MR>Gear ed							
13/04/25	13/04/25 09:14	413/04/25 10:4	8 (D4) Door Closer -Weight/Rope/Spirator /Spring/Arm	r							
INDIA4378081	1 13/04/25 09:18	5	(K4) Component Damaged / Broken / Stripped (A1) Adjusted / Repaired								
6280985652, 6280985652		12.0 Minutes	(Aasif ., Rajkumar Singh) D4 : K4 : A1 Door Closer -Weight/Rope/Spirator /Spring/Arm Component Damaged / Broken / Stripped								
			Lift was not working, Problem:- 3rd floor landing door spring break Damaged, Action:- 3rd floor spring repair now lift								

working condition ok

(CALLER) PROBLEM CUSTOM

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers Or EC - Only VFM Receive				_	able, N	OF - N	No
1183924	20:33		(ramavtar) not working	g 45 GR (2-13 -S15988) - Elevator> MR>Gear ed				_ €	i <sup>-</sup> ⊏	]_8
19/04/25	19/04/25 20:3	35 19/04/25 21:4	5 (CX) Controller-Other							]
INDIA439513	2 19/04/25 20:3	35	(K2) Communication Fault (AX) Action - Other							
8285216555		2.0 Minutes	(Raja .) CX : K2 : AX Controller-Other Communication Fault Lift was not working Error- N/A Action- limit switch communication problem and controller wiring need	No						

CALL

CALL	LOGGED		(CALLER) PROBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, No	OF - N	lo	
1185954	01:26		(ram ) indicator buttor lissue ight not working					_ Ø	<sup>-</sup>	[ <u> </u>	
26/04/25	26/04/25 01:	34 26/04/25 01:5	9 (C8) Power Supply / Transformer / Rectifie	r				$\square$			
INDIA441090	5 26/04/25 01:	35	(KK) No Power / Phase Loss (AA) Tested Operation / No Fault Found								
8285216555, 8285216555		9.0 Minutes	(Raja .) C8 : KK : AA Power Supply / Transformer / Rectifie No Power / Phase Loss								
			Lift was working condition, power supply failure issue, check all basically points no problem found inform to tower guard lift is working condition ok check also power supply lift is working condition o	k							

CALL

CALL	LOGGED		(CALLER) FROBLEW	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	able, N	OF - N	lo	
1187476	20:38		(ramavtar) Lift not working	45 GR (2-13 -S15988) - Elevator> MR>Gear ed				_	_ _ _	[ <u></u>	
30/04/25	30/04/25 20:4	6 30/04/25 20:5	7 (EX) Lift Car - Other					$\overline{\mathscr{C}}$	_	I <sup>_</sup>	
INDIA442437	0 30/04/25 20:5	54	(KZ) Running at Arrival and No Fault Found (AA) Tested Operation / No Fault Found								
8285216555		16.0 Minutes	(Sohan Veer Singh) EX : KZ : AA Lift Car - Other Running at Arrival and No Fault Found	No							
			Lift is not working due to many time power failure, but when we are reached and found that lift os working fine ok after power supply is stable								

CALL

			(	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP	SWP			REC	
						MAX	SWPOA	CHG		REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	able, No	OF - N	lo	
Lift No. All >	47 GR					STP MAX	SWP SWPOA			REC REJ	
1181962	17:51		(singh) lift not working	144 GR (2-13 -S16119) - Elevator> MR>Gear ed				<u> </u>	_		
13/04/25	13/04/25 18:	15 13/04/25 18:5	9 (EX) Lift Car - Other						_		
INDIA437868	33 13/04/25 18:	37	(KZ) Running at Arrival and No Fault Found (AA) Tested Operation / No Fault Found								
9968656672, 9968656672		46.0 Minutes	(Saurabh Kumar) EX : KZ : AA Lift Car - Other Running at Arrival and No Fault Found Lift running on arrival								
			Lift running on arrival we are checked lift								

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA	-	_	REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	•		uck With Passengers Or EC - Only VFM Receive				•	able, N	OF - N	lo
Lift No. All > 4	8 GR					STP MAX	SWP SWPOA		_	REC REJ
1187117	16:02		(PRAMOD) Im-16036 and 16035 BOTH LIFTS ARE NOT WORKING	35 GR (2-13 -S16036) - Elevator> MR>Gear ed						
29/04/25	29/04/25 17:5	52 29/04/25 18:0	1 (D6) Door Panel							
INDIA442064	7 29/04/25 17:5	57	(K2) Communication Fault (A1) Adjusted / Repaired							
8954952422, 8920799565		1.9 Hours	(Rajkumar Singh) D6 : K2 : A1 Door Panel Communication Fault Lift was not working error code N/A Reason of failure car door starks Corrective action-now car door track roller new replace elevator working now ok							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	•		uck With Passengers O EC - Only VFM Receive				•	able, No	OF - N	lo	
Lift No. All > 5	5 GR					STP MAX	SWP SWPOA			REC REJ	
1186213	19:43		(Suhas Chand ) Lift not working properly.	12 GR (2-13 -S16015) - Elevator> MR>Gear ed							
26/04/25	26/04/25 19:5	326/04/25 20:3	9 (C3) Contactor/Relay/Time	r							
INDIA441384	8 26/04/25 20:1	1	(K2) Communication Fault (A4) Cleaned								
9639569589, 9639569589	56.0 Minutes	28.0 Minutes	(Raja .) C3 : K2 : A4 Contactor/Relay/Time Communication Fault Lift was not working Error- N/A Action- main contactor no point problem no point clean now lift working condition ok								

CALL

CALL

OALL	LOGGLD		(CALLER) I ROBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		cuck With Passengers Or REC - Only VFM Receive				_	ible, N	OF - N	lo	
1181954	17:07		(Jagat singh) Car light is not working	: 51 GR (2-13 -S16037) - Elevator> MR>Gear ed				_	( <sup>-</sup> =	<u> </u>	
13/04/25	13/04/25 18:	57 13/04/25 19:0	03 (E8) Lighting / Ventilation						_ [	I	
INDIA4378686	6 13/04/25 18:	59	(K4) Component Damaged / Broken / Stripped (A1) Adjusted / Repaired								
9456238544, 9456238544		1.9 Hours	(Saurabh Kumar) E8 : K4 : A1 Lighting / Ventilation Component Damaged / Broken / Stripped								
			4core traveling cable wire puch so car light now glowing, now cable repaired done and car light is								

working fine

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers Or EC - Only VFM Receive				_	able, N	OF - N	lo
1187171	19:20		(Shrivastav) Lift not working	51 GR (2-13 -S16037) - Elevator> MR>Gear ed				_	_⊾	
29/04/25	29/04/25 19:	50 29/04/25 19:5	9 (EX) Lift Car - Other					₹		
INDIA442105	4 29/04/25 19:	50	(KZ) Running at Arrival and No Fault Found (AA) Tested Operation / No Fault Found							
9958968080		30.0 Minutes	(Raja .) EX : KZ : AA Lift Car - Other Running at Arrival and No Fault Found							
			Lift found in running condition when we are reached, and check lift 20 mint running but no fault found, lit working fine							

CALL

			ER UNIT						
CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			
IN	SWP REL								
TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
-		-				_	ıble, N	OF - N	lo
52 GR					STP MAX	SWP SWPOA			
11:57		(singh) door issue. button not working.	52 GR (2-13 -S16038) - Elevator> MR>Gear ed						
07/04/25 12:1	7 07/04/25 14:5	5 (E1) C.O.P Buttons/Keyswitches/ Indicators/Display/P CB							
8 07/04/25 13:4	16	(K2) Communication Fault (A7) Reset and Tested	i						
	1.8 Hours	(Sohan Veer Singh) E1: K2: A7 C.O.P Buttons/Keyswitches/ Indicators/Display/P CB Communication Fault 1st floor display problem Display wire reconnect	No						
	IN  TIME STOPPED  With Passenge all cancelled, Since 11:57  07/04/25 12:1	IN SWP REL  TIME RESPONSE STOPPED TIME  With Passengers, SWPOA - Strall cancelled, STP - Stopped, R  52 GR  11:57  07/04/25 12:17 07/04/25 14:5	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) ACTION  With Passengers, SWPOA - Stuck With Passengers Or all cancelled, STP - Stopped, REC - Only VFM Received (S2 GR)  11:57 (singh) door issue. button not working.  07/04/25 12:17 07/04/25 14:55 (E1) C.O.P Buttons/Keyswitches/Indicators/Display/P CB  8 07/04/25 13:46 (K2) Communication Fault (A7) Reset and Tested (A7) Reset and Tested (A7) Reset (Sohan Veer Singh) E1: K2: A7 C.O.P Buttons/Keyswitches/Indicators/Display/P CB Communication Fault 1st floor display problem Display wire	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS MATERIA L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/r all cancelled, STP - Stopped, REC - Only VFM Received Calls, RE  32 GR  11:57 (singh) door issue. 52 GR button not working. (2-13 - S16038) - Elevator> MR>Gear ed  07/04/25 12:17 07/04/25 14:55 (E1) C.O.P Buttons/Keyswitches/ Indicators/Display/P CB  8 07/04/25 13:46 (K2) Communication Fault (A7) Reset and Tested  1.8 Hours (Sohan Veer Singh) No E1: K2: A7 C.O.P Buttons/Keyswitches/ Indicators/Display/P CB  Communication Fault  1st floor display problem Display wire	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hou all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ -	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Reject S2 GR  STP MAX  11:57 (singh) door issue. 52 GR button not working. (2-13 - S16038) - Elevator> MR>-Gear ed  07/04/25 12:17 07/04/25 14:55 (E1) C.O.P Buttons/Keyswitches/ Indicators/Display/P CB  8 07/04/25 13:46 (K2) Communication Fault (A7) Reset and Tested  1.8 Hours (Sohan Veer Singh) No E1: K2: A7 C.O.P Buttons/Keyswitches/ Indicators/Display/P CB Communication Fault (A7) Reset and Tested	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargea all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls S2 GR  STP SWP MAX SWPOA  11:57 (singh) door issue. 52 GR button not working. (2-13 - S16038) - Elevator - MR-Gear ed  07/04/25 12:17 07/04/25 14:55 (E1) C.O.P Buttons/Keyswitches/ Indicators/Display/P CB  8 07/04/25 13:46 (K2) Communication Fault (A7) Reset and Tested  1.8 Hours (Sohan Veer Singh) No E1: K2: A7 C.O.P Buttons/Keyswitches/ Indicators/Display/P CB C Communication Fault 1st floor display problem Display wire	CONFIRM OUT (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA STOPPED TIME ACTION MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Charge-able, No all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  S2 GR  STP SWP A/H MAX SWPOA CHG  11:57 (singh) door issue. 52 GR button not working. (2-13 - S16038) - Elevator> MR>-Gear ed  07/04/25 12:17 07/04/25 14:55 (E1) C.O.P- Buttons/Keyswitches/ Indicators/Display/P CB  1.8 Hours (Sohan Veer Singh) No E1 : K2 : A7 C.O.P Buttons/Keyswitches/ Indicators/Display/P CB  Communication Fault 1st floor display problem Display wire	CONFIRM OUT (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA STOPPED TIME ACTION MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - Nall cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  32 GR  STP SWP A/H NOF MAX SWPOA CHG CC  11:57 (singh) door issue. 52 GR button not working. (2-13 - S16038) - Elevator> MR>Gear ed  07/04/25 12:17 07/04/25 14:55 (E1) C.O.P- Buttons/Keyswitches/ Indicators/Display/P CB  8 07/04/25 13:46 (K2) Communication Fault (A7) Reset and Tested  1.8 Hours (Sohan Veer Singh) No E1: K2: A7 C.O.P- Buttons/Keyswitches/ Indicators/Display/P CB  COmmunication Fault  1 st floor display problem Display wire

Working now

(CALLER) PROBLEM CUSTOM

CALL

CALL	LOGGED		(CALLER) PROBLEM	ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	lo
1182265	17:50		(Jagat singh) Not working	52 GR (2-13 -S16038) - Elevator> MR>Gear ed				_	<sup>-</sup> -	_ 
14/04/25	14/04/25 18:0	0 14/04/25 18:2	7 (SX) Shaft - Other						_	
INDIA4380938	3 14/04/25 18:0	7	(K2) Communication Fault (AX) Action - Other							
9456238544, 9456238544	37.0 Minutes	17.0 Minutes	(Raja .) SX : K2 : AX Shaft - Other Communication Fault Lift was not working Error- N/A Action- car door sensor adjust now lift working condition ok	No						
1183094	10:23		(JAGATH) DOOR NOT WORKING	52 GR (2-13 -S16038) - Elevator> MR>Gear ed						
17/04/25	17/04/25 10:3	8 17/04/25 12:0	5 (SX) Shaft - Other							
INDIA4387238	3 17/04/25 10:3	8	(K2) Communication Fault (AX) Action - Other							
9456238544, 8920799565		15.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault	No						
			Elevator stop at 3rd floor close relay problem relay clean elevator working							

CALL

Lift was not working

Error-N/A
Action- Brack
contactor no point
problem no point
clean now lift working

condition ok

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP	SWP			REC	
						MAX	SWPOA	CHG	СС	REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	ıble, N	OF - N	lo	
Lift No. All > 5	54 GR					STP MAX	SWP SWPOA		_	REC REJ	
1179123	19:44		(Kumar ) Lift not working and error.	54 GR (2-13 -S16040) - Elevator> MR>Gear ed							
04/04/25	04/04/25 21:	46 04/04/25 21:5	50 (DX) Door - Other								
INDIA435863	6 04/04/25 21:	47	(K2) Communication Fault (AX) Action - Other								
9720672130, 9720672130	2.1 Hours	2.1 Hours	(Aasif .) DX : K2 : AX Door - Other Communication Fault	No							
			Communication Fault wiring check required lift under shutdown								

CALL

LOGGED		(CALLER) FROBLEW	ER UNIT						
CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			
IN	SWP REL								
TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
-		_				_	able, N	OF - N	lo
13:54		(dharmendra) door issue	54 GR (2-13 -S16040) - Elevator> MR>Gear ed					ı <sup>-</sup> ⊏	I <sup>-</sup>
08/04/25 14:	12 08/04/25 16:1	` '	r						
6 08/04/25 14:	12	(K4) Component Damaged / Broken / Stripped (A9) Switched Off for Repairs							
	18.0 Minutes	Contactor/Relay/Time	r						
		Lift was not working, Error 29, 23 and break not open, bk contactor no, no point problem contactor need to be replaced contactor required, lift under shutdown for repair							
	CONFIRM  IN  TIME STOPPED  With Passenge all cancelled, S  13:54	CONFIRM OUT  IN SWP REL  TIME RESPONSE STOPPED TIME  With Passengers, SWPOA - Strall cancelled, STP - Stopped, R  13:54  08/04/25 14:12 08/04/25 16:1	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) ACTION  With Passengers, SWPOA - Stuck With Passengers Orall cancelled, STP - Stopped, REC - Only VFM Received  13:54 (dharmendra) door issue  08/04/25 14:12 08/04/25 16:18 (C3) Contactor/Relay/Time  6 08/04/25 14:12 (K4) Component Damaged / Broken / Stripped (A9) Switched Off for Repairs  18.0 Minutes (Aasif.) C3: K4: A9 Contactor/Relay/Time Component Damaged / Broken / Stripped Lift was not working, Error 29, 23 and break not open, bk contactor no, no point problem contactor need to be replaced contactor required, lift under	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS MATERIA L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/Fall cancelled, STP - Stopped, REC - Only VFM Received Calls, RE  13:54 (dharmendra) door issue (2-13 - S16040) - Elevator> MR>Gear ed  08/04/25 14:12 08/04/25 16:18 (C3) Contactor/Relay/Timer  6 08/04/25 14:12 (K4) Component Damaged / Broken / Stripped (A9) Switched Off for Repairs  18.0 Minutes (Aasif.) C3: K4:A9 No Contactor/Relay/Timer Component Damaged / Broken / Stripped  Lift was not working, Error 29, 23 and break not open, bk contactor no, nc point problem contactor need to be replaced contactor required, lift under	CONFIRM OUT (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA ACTION MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hou all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM received recei	CONFIRM OUT (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Reject  13:54 (dharmendra) door 54 GR (ssue (2-13 - S16040) - Elevator> MR>Gear ed  08/04/25 14:12 08/04/25 16:18 (C3) Contactor/Relay/Timer  6 08/04/25 14:12 (K4) Component Damaged / Broken / Stripped (A9) Switched Off for Repairs  18.0 Minutes (Aasif.) C3: K4:A9 No Contactor/Relay/Timer Component Damaged / Broken / Stripped  Lift was not working, Error 29, 23 and break not open, bk contactor no , nc point problem contactor need to be replaced contactor required, lift under	CONFIRM OUT	CONFIRM OUT	CONFIRM OUT

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - I	No	
1181697	19:33		(Dharmendra) Not working	54 GR (2-13 -S16040) - Elevator> MR>Gear ed					ſ <sup>-</sup> ⊏	]	
12/04/25	12/04/25 20:1	11 12/04/25 21:2	4 (C3) Contactor/Relay/Time	r					]_[	]	
INDIA437789	8 12/04/25 20:′	17	(K2) Communication Fault (AX) Action - Other								
9720672130, 9720672130	1.9 Hours	44.0 Minutes	(Raja .) C3 : K2 : AX Contactor/Relay/Time Communication Fault	r							
			Lift was not working Error- H29 Bk contactor communication problem								

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Oi EC - Only VFM Receive				•	ıble, N0	OF - N	0	
Lift No. All >	55 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1178427	19:06		(Ramesh) Stuck issue	157 GR (2-13 -S16132) - Elevator> MR>Gear ed				_ 	₩		
02/04/25	02/04/25 19:	40 02/04/25 20:2	0 (EX) Lift Car - Other					$\overline{\mathscr{A}}$			
INDIA435303	37 02/04/25 19:	52	(KZ) Running at Arrival and No Fault Found (AA) Tested Operation / No Fault Found								
7409975120		46.0 Minutes	(Aasif., Saurabh Kumar) EX: KZ: AA Lift Car - Other Running at Arrival and No Fault Found Lift check but no any problem found, working condition ok, checked all basically	No							

point

(CALLER) PROBLEM CUSTOM

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				-	ible, N	OF - N	lo	
Lift No. All > 5	7 GR					STP MAX	SWP SWPOA		_	REC REJ	
1186409	14:09		not working	57 GR (2-13 -S15996) - Elevator> MR>Gear ed							
27/04/25	27/04/25 14:3	36 27/04/25 15:3	8 (SX) Shaft - Other					$ \mathbf{Z} $			
INDIA441455	9 27/04/25 14:3	37	(K2) Communication Fault (AX) Action - Other								
6396482052, 6396482052		28.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault Elevator stop at 3rd floor customer miss use car door out of track car door roller damage new car door roller changed								

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				-	able, No	OF - N	lo	
Lift No. All > 5	58 GR					STP MAX	SWP SWPOA			REC REJ	
1185792	14:01		(bijender) lift is not working	58 GR (2-13 -S15997) - Elevator> MR>Gear ed							
25/04/25	25/04/25 14:	1625/04/25 14:4	3 (C4) Controller Wiring	ı							
INDIA440935	5 25/04/25 14:	16	(K2) Communication Fault (AX) Action - Other								
7838072706, 7838072706		15.0 Minutes	(Rajkumar Singh) C4 : K2 : AX Controller Wiring Communication Fault Lift was not working Error-N/A Action- car door adjust now lift working								

CALL

CALL	LOGGED		(CALLER) PROBLEM	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	able, No	OF - N	lo	
Lift No. All > 6	1 GR					STP MAX	SWP SWPOA			REC REJ	
1182936	17:47		(Priti) Not working	14 GR (2-13 -S16017) - Elevator> MR>Gear ed		<u> </u>		<u> </u>		I_⊠.	
16/04/25	16/04/25 17:5	116/04/25 18:00	O (D4) Door Closer -Weight/Rope/Spirator /Spring/Arm							I	
INDIA4386118	3 16/04/25 17:5	1	(K2) Communication Fault (A1) Adjusted / Repaired								
9911509845, 9911509845	13.0 Minutes	4.0 Minutes	(Raja .) D4 : K2 : A1 Door Closer -Weight/Rope/Spirator /Spring/Arm Communication Fault								
			Lift was not working Error- N/A Action- Ground floor landing door spring repair now lift working condition ok								

CALL

CALL	LOGGED		(CALLER) PROBLEM	ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O EC - Only VFM Receive				_	able, No	OF - N	О
1185817	15:10		(Mobile app) 2V lift 61 not working.	61 GR (2-13 -S16000) - Elevator> MR>Gear ed					_	·
25/04/25	25/04/25 15:2	6 25/04/25 15:5	4 (EX) Lift Car - Other					$\checkmark$		
INDIA4409662	2 25/04/25 15:2	6	(KZ) Running at Arrival and No Fault Found (AX) Action - Other							
8447091893, 8447091893	44.0 Minutes	16.0 Minutes	(Raja .) EX : KZ : AX Lift Car - Other Running at Arrival and No Fault Found  Lift running condition no fault found Check 30 minutes							
Lift No. All > 6	2 GR					STP	SWP	A/H	NOF	REC
						MAX	SWPOA	CHG	CC	REJ
1179987	14:00		(Mobile App) 2W lift 62 not working	62 GR (2-13 -S16001) - Elevator> MR>Gear ed		Ø				
07/04/25	07/04/25 14:0	8 07/04/25 15:0	6 (SX) Shaft - Other					$\square$		
INDIA436303	1 07/04/25 14:1	0	(K2) Communication Fault (AX) Action - Other							
8447091893, 8447091893	1.1 Hours	10.0 Minutes	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault	No						
			Elevator running on arrival							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	I							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	-		uck With Passengers Or EC - Only VFM Receive				•	ible, N	OF - N	No	
Lift No. All > 6	3 GR					STP MAX	SWP SWPOA		_	REC REJ	
1178576	10:25		(Sanjay) door issue	63 GR (2-13 -S16041) - Elevator> MR>Gear ed						]	
03/04/25	03/04/25 10:3	34 03/04/25 11:3	3 (SX) Shaft - Other							]	
INDIA435356	1 03/04/25 11:2	28	(K2) Communication Fault (AX) Action - Other								
8920242931, 8920242931		1.1 Hours	(Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault Car door sensor some time problem elevator need to be check and foult clear								

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
			uck With Passengers O EC - Only VFM Receive					able, N	OF - N	lo	
1179663	14:51		(sanjay ) 2nd floor lift got struck	63 GR (2-13 -S16041) - Elevator> MR>Gear ed							
06/04/25	06/04/25 15:1	8 06/04/25 16:0	6 (SJ) Traveling Cable -Wiring/Hitches/Termi nal Connections								
INDIA436137	8 06/04/25 15:5	57	(K4) Component Damaged / Broken / Stripped (A9) Switched Off for Repairs								
8920242931, 8920242931		1.1 Hours	(Aasif .) SJ : K4 : A9 Traveling Cable -Wiring/Hitches/Termi nal Connections Component Damageo / Broken / Stripped								
			Lift was not working cop call nit accept, and high voltage traveling cable damaged, need to be check lift under shutdown for checking								

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	I							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
			uck With Passengers Or EC - Only VFM Receive					able, N	OF - N	lo .	
1184746	12:29		(Sanjay ) Display problem	63 GR (2-13 -S16041) - Elevator> MR>Gear ed					-	]_ <u>@</u> _	
22/04/25	22/04/25 12:	33 22/04/25 13:1	8 (S8) Landing Arrival & Position -Fixture/Display/Gong /Indication/PCB						I <sup>-</sup> -	]	
INDIA439984	8 22/04/25 12:4	49	(K2) Communication Fault (A1) Adjusted / Repaired								
8920242931, 8920242931		20.0 Minutes	(Pushpender Singh, Saurabh Kumar) S8: K2: A1 Landing Arrival & Position -Fixture/Display/Gong /Indication/PCB Communication Fault 7th floor display digit cut, display wiring reconnect and display reconnect, now display is working fine and display digit show properly (asif)								

CALL

CALL	LOGGED		(CALLER) PROBLEM	ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers Or EC - Only VFM Receive				-	able, N	OF - N	lo
1187090	14:44		(sanjay) LM-16041-COP BUTTON NOT WORKING	63 GR (2-13 -S16041) - Elevator> MR>Gear ed					<sup>-</sup> ₩	_ <u>&amp;_</u>
29/04/25	29/04/25 14:5	53 29/04/25 16:5	2 (EX) Lift Car - Other					₩		
INDIA4420117	7 29/04/25 16:0	05	(KZ) Running at Arrival and No Fault Found (AX) Action - Other							
8920242931, 8920799565		1.4 Hours	(Raja .) EX : KZ : AX Lift Car - Other Running at Arrival and No Fault Found							
			Lift running on arrival no fault found button working condition ok							
1187299	10:28		(SANJAY) DISPLAY NOT WORKING ON 7TH FLOOR	63 GR (2-13 -S16041) - Elevator> MR>Gear ed					I <sup>-</sup> □	
30/04/25	30/04/25 10:4	17 30/04/25 11:3	4 (SX) Shaft - Other							
INDIA442172	7 30/04/25 11:3	32	(K2) Communication Fault (AX) Action - Other							
8920242931, 8920799565		1.1 Hours	(Raja .) SX : K2 : AX Shaft - Other Communication Fault	No						
			Lift was not working Error- N/A Action- controller wiring need to check required							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	ible, N	OF - N	lo	
Lift No. All > (	64 GR					STP MAX	SWP SWPOA			REC REJ	
1186670	11:47		(Sanjay) Lift not working	64 GR (2-13 -S16042) - Elevator> MR>Gear ed							
28/04/25	28/04/25 12:		7 (DX) Door - Other								
INDIA441615	54 28/04/25 13:	09	(K2) Communication Fault (A1) Adjusted / Repaired								
8920242931		1.4 Hours	(Raja .) DX : K2 : A1 Door - Other Communication Fault Lift was not working Error- N/A Action- car door Scket								
			adjust but landing door roller tuch to car sil lift under shutdown								

CALL

07122	200025		(0/12211)	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA	A/H CHG			
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	ıble, NO	OF - N	lo	
Lift No. All > 6	7 GR					STP MAX	SWP SWPOA	A/H CHG		REC REJ	
1178332	13:40		(Mobile App) GVI CLUB 162 LIFT VIBRATION IN RUNNING TIME.	162 GR (2-13 -S15975) - Elevator> MR>Gear ed					✓		
02/04/25	02/04/25 14:1	202/04/25 15:1	1 (EX) Lift Car - Other					$ \mathbf{A} $			
INDIA435174	5 02/04/25 14:4	3	(KZ) Running at Arrival and No Fault Found (AA) Tested Operation / No Fault Found								
8447091893, 8447091893		1.1 Hours	(Aasif ., Saurabh Kumar) EX: KZ: AA Lift Car - Other Running at Arrival and No Fault Found	No d							
			Customer complain is running time vibration but we are checked lift running many times with preset guard but no vibration coming in lift while running time, lift is running smoothly	,							

CALL

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	•		uck With Passengers Or EC - Only VFM Receive				•	ble, N	OF - N	0
1183383	08:48		(vikram singh) lift door is not closing properly					_		
18/04/25	18/04/25 08:5	53 18/04/25 10:2	8 (SX) Shaft - Other						_	
INDIA438979	5 18/04/25 08:5	53	(K2) Communication Fault (AX) Action - Other							
8375923674, 8375923674		5.0 Minutes	(Naresh Kumar, Sanjay Verma) SX: K2: AX Shaft - Other Communication Fault Elevator not working stop at ground floor landing door safety not coming and door drive problem door drive need to be replace elevator shutdown	No						

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				_	able, N	OF - N	10	
Lift No. All > 7	′1 GR					STP MAX	SWP SWPOA			REC REJ	
1187417	16:26		(Kapil kumar) lift getting stuck at 1st floor frequently	71 GR (2-13 -S16049) - Elevator> MR>Gear ed						1 ⊠	
30/04/25	30/04/25 16:5	5430/04/25 18:0	3 (D6) Door Panel								
INDIA442391	7 30/04/25 16:5	54	(K2) Communication Fault (A1) Adjusted / Repaired								
8860346827, 8860346827		28.0 Minutes	(Rajkumar Singh) D6: K2: A1 Door Panel Communication Fault Lift is working now but 1st floor landing lop waring reconnect elevator working now	No							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	lo	
Lift No. All > 7	72 GR					STP MAX	SWP SWPOA			REC REJ	
1178097	19:28		(Mitesh Singh) Door is not opening at 6th floor	s 72 GR (2-13 -S16050) - Elevator> MR>Gear ed							
01/04/25	01/04/25 20:3	35 01/04/25 20:47	7 (DX) Door - Other								
INDIA435029	9 01/04/25 20:3	36	(K2) Communication Fault (AX) Action - Other								
9899794790, 9899794790		1.1 Hours	(Hovendra Kumar) DX: K2: AX Door - Other Communication Fault Lift running on arrival in time on testing customer was log complain by mistake in								

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers Or EC - Only VFM Receive				-	able, N	OF - N	lo	
1185164	15:14		(Kapil Kumar) Both lift moving on same time							_ <u>_</u>	
23/04/25	23/04/25 15:3	31 23/04/25 16:1	0 (CX) Controller-Other					_			
INDIA440364	7 23/04/25 15:4	14	(KV) Software Fault / PCB Lock Up (AX) Action - Other								
8860346827, 8920799565		30.0 Minutes	(Pushpender Singh, Saurabh Kumar) CX: KV: AX Controller-Other Software Fault / PCB Lock Up Both lift is working but duplex system is not working, so we need programming Eprom and duplex wiring need to be check,								

CALL

(CALLER) PROBLEM CUSTOM CALL **LOGGED ER UNIT** STP A/H NOF REC DATE **CONFIRM** OUT (NO.) FAULT **SWP** MAX SWPOA CHG CC REJ DOCKET **SWP REL** (NO.) FAULT CAUSE IN (NO.) FAULT ACTION CONTACT TIME **RESPONSE** (TECHNICIAN) **LIFTUSA** IS **STOPPED** TIME **ACTION** MATERIA GE L USED SWP - Stuck With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - No Fault, CC - Call cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls Lift No. All > 73 GR STP **SWP** A/H NOF REC SWPOA CHG CC MAX REJ M  $\square$ 1179738 20:08 (Verma) 9999027690 73 GR S16052 also not (2-13)working -S16051) -Elevator> MR>Gear ed 06/04/25 06/04/25 20:19 06/04/25 21:23 (D5) Door Operator -Motor / Gear Box / Belt / Chain / Static Drive INDIA4361687 06/04/25 20:19 (K2) Communication Fault (A9) Switched Off for Repairs 9999027690, 1.3 Hours 11.0 Minutes (Hovendra Kumar) No 9999027690 D5: K2: A9 Door Operator - Motor / Gear Box / Belt / Chain / Static Drive Communication Fault Check the lift condition door not open need to be check properly elevator is shutdown for checking Lift No. All > 77 GR **STP SWP** A/H NOF REC SWPOA CHG CC MAX REJ  $\mathbf{Z}$ 1179537 (Chaman) Lift Fan 09:38 issue  $\square$ 06/04/25 Cust omer canc el call 9675707008, 0 (Raja .) :: No 9675707008

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA		NOF CC	REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, No	OF - N	lo	
Lift No. All > 8	80 GR					STP MAX	SWP SWPOA	A/H CHG		REC	
1181712	20:40		(Pankaj) Alarm not working	79 GR (2-13 -S16057) - Elevator> MR>Gear ed						]	<b>1</b>
12/04/25	12/04/25 21:2	25 12/04/25 21:5	3 (S6) Floor PCB						_	]_[	]
INDIA437792	24 12/04/25 21::	25	(K2) Communication Fault (A1) Adjusted / Repaired								
9654589522		45.0 Minutes	(Raja .) S6 : K2 : A1 Floor PCB Communication Fault Lift was working condition 2floor lop not working 2floor landing display rewiring now button working condition ok	No							

LOGGED

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
			uck With Passengers Or EC - Only VFM Receive					ıble, N	OF - N	lo
1184583	08:19		(Trivedi) Lift not working	80 GR (2-13 -S16058) - Elevator> MR>Gear ed				_ _		_ <u>~</u>
22/04/25	22/04/25 08:3	35 22/04/25 09:5	0 (D6) Door Panel							
INDIA439935	0 22/04/25 09:′	13	(K7) Component or Connection - Loose (A1) Adjusted / Repaired							
9968212139, 9968212139	1.5 Hours	54.0 Minutes	(Aasif ., Raja .) D6: K7: A1 Door Panel Component or Connection - Loose  Lift was working but Some time ground floor Landing door not closed and Landing latch not fix properly  Action Ground floor landing door latch repair and door adjusted now lift working condition and							

CALL

(CALLER) PROBLEM CUSTOM CALL **LOGGED ER UNIT** DATE **CONFIRM** OUT (NO.) FAULT **STP SWP** A/H NOF REC MAX SWPOA CHG CC REJ (NO.) FAULT CAUSE DOCKET **SWP REL** IN (NO.) FAULT ACTION CONTACT TIME **RESPONSE** (TECHNICIAN) **LIFTUSA** IS **STOPPED** TIME **ACTION** MATERIA GE L USED SWP - Stuck With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - No Fault, CC - Call cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls Lift No. All > 83 GR STP **SWP** A/H NOF REC SWPOA CHG CC MAX REJ M 1177882 09:44 (SARVESH) LIFT 95 GR **NOT WORKING** (2-13)-S16072) -Elevator> MR>Gear ed 01/04/25 01/04/25 09:49 01/04/25 11:02 (SX) Shaft - Other INDIA4348166 01/04/25 10:21 (K2) Communication Fault (AX) Action - Other 6306276675, 37.0 Minutes (Sanjay Verma) SX: No 8920799565 K2: AX Shaft - Other Communication Fault Elevator stop at 5th floor permanent Ground show set switch problem set switch clean elevator working ok 1179263 10:35 (rohit) not working 83 GR (2-13)-S16061) -Elevator> MR>Gear ed 05/04/25 05/04/25 10:38 05/04/25 11:40 (ZX) No Fault Found INDIA4359049 05/04/25 10:58 (K2) Communication Fault (AA) Tested Operation / No Fault Found 23.0 Minutes (Rajkumar Singh) ZX No 9536160214, 8920799565 : K2 : AA No Fault Found Communication Fault Lift was working condition running on arrival

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O EC - Only VFM Receive				_	ıble, N	OF - N	lo
1184553	00:41		(Shukla) Lift not working	83 GR (2-13 -S16061) - Elevator> MR>Gear ed				_ ₩		1 ☑
22/04/25	22/04/25 02:2	21 22/04/25 06:2	9 (PX) Drive - Other							I <sup>-</sup>
INDIA439930	0 22/04/25 06:2	20	(K2) Communication Fault (A9) Switched Off for Repairs							
9319504219, 9319504219		5.7 Hours	(Hovendra Kumar) PX: K2: A9 Drive - Other Communication Fault Lift was not working Fault. Error 101 coming Action. Lift running time inspection show now inspection switch nc point clean now elevator working fine							

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	•		uck With Passengers O EC - Only VFM Receive				•	able, N	OF - N	lo
1184700	11:21		(Rohit Kumar ) Stuck On 8th Floor Not Working	83 GR (2-13 -S16061) - Elevator> MR>Gear ed						_⊠_
22/04/25	22/04/25 12:2	23 22/04/25 13:0	8 (CX) Controller-Other							
INDIA439980	0 22/04/25 13:0	)2	(K2) Communication Fault (A9) Switched Off for Repairs							
9536160214, 9536160214		1.7 Hours	(Rajkumar Singh) CX: K2: A9 Controller-Other Communication Fault Lift was not working, fault unknown, And door was not closed at 8th floor need to be check properly so lift under shutdown for repair/ Check							

CALL

CALL	LOGGED		(CALLER) FROBLEN	ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	-		uck With Passengers O EC - Only VFM Receive				_	able, No	OF - N	lo	
Lift No. All > 8	38 GR					STP MAX	SWP SWPOA			REC REJ	
1180736	20:12		(Arun ) Button not working	88 GR (2-13 -S16066) - Elevator> MR>Gear ed						I ⊠	
09/04/25	09/04/25 20:2	27 09/04/25 20:4	9 (S6) Floor PCB								
INDIA436960	8 09/04/25 20:2	29	(K4) Component Damaged / Broken / Stripped (A1) Adjusted / Repaired								
9319504219		17.0 Minutes	(Rajkumar Singh) S6 : K4 : A1 Floor PCB Component Damaged / Broken / Stripped								
			Lift was working Fault 4th floor cop button not working Corrective action-now button pcb damage other use pcb working now ok								

CALL

				ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers O				_	ble, NO	OF - N	lo
1186346	11:11		(Mr. prakash) Lift not working stuck on third floor							I_⊠
27/04/25	27/04/25 11:4	41 27/04/25 12:2	8 (C3) Contactor/Relay/Time	r						I <sup>-</sup>
INDIA441421	4 27/04/25 11:	43	(K2) Communication Fault (AX) Action - Other							
9675707008, 8920799565		32.0 Minutes	(Raja .) C3 : K2 : AX Contactor/Relay/Time Communication Fault Lift was not working Error-N/A	r						
			Action- mc1 contactor no point problem no point change now lift working condition ok							

CALL

				ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		uck With Passengers O EC - Only VFM Receive				_	able, N	OF - N	lo	
Lift No. All > 8	89 GR					STP MAX	SWP SWPOA			REC REJ	
1185155	14:34		(Samart) Lift not working	89 GR (2-13 -S16067) - Elevator> MR>Gear ed		<u> </u>					
23/04/25	23/04/25 14:	39 23/04/25 15:4	4(E1) C.O.P Buttons/Keyswitches/ Indicators/Display/P CB							I	
INDIA440352	28 23/04/25 14:	40	(K2) Communication Fault (A1) Adjusted / Repaired								
8826682291, 8826682291	1.2 Hours	6.0 Minutes	(Pushpender Singh, Saurabh Kumar) E1: K2: A1 C.O.P Buttons/Keyswitches/ Indicators/Display/P CB Communication Fault Lift is working but car display not working due to display contactor loose, now connector fixed properly and disis working fine								

CALL

**ER UNIT** DATE **CONFIRM** OUT (NO.) FAULT **STP SWP** A/H NOF REC MAX SWPOA CHG CC REJ DOCKET **SWP REL** (NO.) FAULT CAUSE IN (NO.) FAULT ACTION CONTACT TIME **RESPONSE** (TECHNICIAN) **LIFTUSA** IS **STOPPED** TIME **ACTION** MATERIA GE L USED SWP - Stuck With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - No Fault, CC - Call cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls Lift No. All > 9 GR STP **SWP** A/H NOF REC SWPOA CHG CC REJ MAX  $\square$  $\square$ 1179159 23:10 9 GR (BHARATH) LIFT **NOT WORKING** (2-13)-S16013) -Elevator> MR>Gear ed 04/04/25 04/04/25 23:10 04/04/25 23:39 (DX) Door - Other INDIA4358688 04/04/25 23:11 (K2) Communication Fault (A1) Adjusted / Repaired 9719373323 1.0 Minute (Raja .) DX : K2 : A1 No Door - Other Communication Fault Lift was not working Error-31 Action- 2 floor landing door contect adjust now lift working condition ok M 1180006 14:53 (Punit Sharma) 9 GR 9205299071 lift not (2-13)working. -S16013) -Elevator> MR>Gear ed 0 O 07/04/25 07/04/25 15:06 07/04/25 16:16 (SX) Shaft - Other INDIA4363333 07/04/25 15:06 (K2) Communication Fault (AX) Action - Other 9205299071, 1.4 Hours (Sanjay Verma) SX: No 13.0 Minutes 8920799565 K2: AX Shaft - Other Communication Fault Elevator running on arrival

(CALLER) PROBLEM CUSTOM

CALL

CALL

CALL

			ER UNIT						
CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA	-		REC REJ
IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION	I						
TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
_		_				_	ble, N	OF - N	lo
95 GR					STP MAX	SWP SWPOA			REC REJ
14:13		( Mobile App) 3L lift 95 some one stuck.	95 GR (2-13 -S16072) - Elevator> MR>Gear ed		Ø				<u> </u>
04/04/25 14:2	5 04/04/25 14:2	Closer							
8 04/04/25 14:2	6	(KN) Out of Adjustment / Alignment (A1) Adjusted / Repaired							
16.0 Minutes	13.0 Minutes	/Spring/Arm Out of Adjustment / Alignment Latch roller tuch with	No						
	IN  TIME STOPPED  With Passenger all cancelled, STOPPED  14:13  04/04/25 14:2	IN SWP REL  TIME RESPONSE STOPPED TIME  With Passengers, SWPOA - Strand cancelled, STP - Stopped, R  95 GR	IN SWP REL (No.) FAULT CAUSE (No.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) STOPPED TIME ACTION  With Passengers, SWPOA - Stuck With Passengers Or all cancelled, STP - Stopped, REC - Only VFM Received Pos GR  14:13 (Mobile App) 3L lift 95 some one stuck.  04/04/25 14:25 04/04/25 14:29 (D4) Door Closer - Weight/Rope/Spirator /Spring/Arm  8 04/04/25 14:26 (KN) Out of Adjustment / Alignment (A1) Adjusted / Repaired  16.0 Minutes 13.0 Minutes (Hovendra Kumar) D4 : KN : A1 Door Closer - Weight/Rope/Spirator /Spring/Arm Out of Adjustment / Alignment out of Adjustment / Alignment (A1) Adjustment / Alignment	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS MATERIA L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/Fall cancelled, STP - Stopped, REC - Only VFM Received Calls, RE.  14:13 (Mobile App) 3L lift 95 GR  95 some one stuck. (2-13 - S16072) - Elevator - MR > Gear ed  04/04/25 14:25 04/04/25 14:29 (D4) Door Closer - Weight/Rope/Spirator / Spring/Arm  8 04/04/25 14:26 (KN) Out of Adjustment / Alignment (A1) Adjusted / Repaired  16.0 Minutes 13.0 Minutes (Hovendra Kumar) No D4 : KN : A1 Door Closer - Weight/Rope/Spirator / Spring/Arm Out of Adjustment / Alignment Latch roller tuch with cupler roller center lift	IN SWP REL (No.) FAULT CAUSE (No.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hou all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM (2-13 - S16072) - Elevator> MR>Gear ed  14:13 (Mobile App) 3L lift 95 GR 95 some one stuck. (2-13 - S16072) - Elevator> MR>Gear ed  04/04/25 14:25 04/04/25 14:29 (D4) Door Closer - Weight/Rope/Spirator /Spring/Arm  8 04/04/25 14:26 (KN) Out of Adjustment / Alignment (A1) Adjusted / Repaired  16.0 Minutes 13.0 Minutes (Hovendra Kumar) No D4 : KN : A1 Door Closer - Weight/Rope/Spirator /Spring/Arm Out of Adjustment / Alignment Latch roller tuch with cupler roller center lift	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Reject (2-13 Sincore) - Elevator - MR>Gear ed  14:13 (Mobile App) 3L lift 95 GR 95 some one stuck. (2-13 Sincore) - Elevator - MR>Gear ed  04/04/25 14:25 04/04/25 14:29 (D4) Door Closer - Weight/Rope/Spirator / Spring/Arm  8 04/04/25 14:26 (KN) Out of Adjustment / Alignment (A1) Adjusted / Repaired  16.0 Minutes 13.0 Minutes (Hovendra Kumar) No D4: KN: A1 Door Closer - Weight/Rope/Spirator / Spring/Arm Out of Adjustment / Alignment Latch roller tuch with cupler roller center lift	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA MATERIA GE L USED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargea all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls and SWPOA  14:13 (Mobile App) 3L lift 95 GR 95 some one stuck. (2-13 - S16072) - Elevator - MR > Gear ed  04/04/25 14:25 04/04/25 14:29 (D4) Door Closer - Weight/Rope/Spirator / Spring/Arm  8 04/04/25 14:26 (KN) Out of Adjustment / Alignment (A1) Adjusted / Repaired  16.0 Minutes 13.0 Minutes (Hovendra Kumar) No D4 : KN : A1 Door Closer - Weight/Rope/Spirator / Spring/Arm Out of Adjustment / Alignment Latch roller tuch with cupler roller center lift	N	IN SWP REL (NO.) FAULT CAUSE (NO.) FAULT ACTION  TIME RESPONSE (TECHNICIAN) IS LIFTUSA GE LUSED  With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Charge=ble, NOF - N all cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls  55 GR  STP SWP A/H NOF MAX SWPOA CHG CC  14:13 (Mobile App) 3L lift 95 GR 95 some one stuck. (2-13 - S16072) - Elevator> MR-Gear ed  04/04/25 14:25 04/04/25 14:29 (D4) Door Closer - Weight/Rope/Spirator /Spring/Arm  8 04/04/25 14:25 (KN) Out of Adjustment / Alignment (A1) Adjusted / Repaired  16.0 Minutes 13.0 Minutes (Hovendra Kumar) No D4 : KN : A1 Door Closer - Weight/Rope/Spirator /Spring/Arm Out of Adjustment / Alignment (A1) Adjusted / Repaired  16.0 Minutes Latch roller tuch with cupler roller center lift

CALL

OALL	LOGGLD		(CALLER) I ROBLEW	ER UNIT						
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION							
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE					
	_		uck With Passengers Or EC - Only VFM Receive				-	ible, N	OF - N	No
1184713	11:35		(Rahul) lift not working	105 GR (2-13 -S16080) - Elevator> MR>Gear ed						]_[2]
22/04/25	22/04/25 12:3	37 22/04/25 14:1	1 (D6) Door Panel							
INDIA4400086	5 22/04/25 13:0	09	(K2) Communication Fault (A9) Switched Off for Repairs							
9627702352, 9627702352	2.6 Hours	1.6 Hours	(Rajkumar Singh) D6 : K2 : A9 Door Panel Communication Fault  Lift was not working, stop at 5th floor Door was closed, check lift condition foind landing door safety problem, need to be check elevator under	No						

CALL

**ER UNIT** DATE **CONFIRM** OUT (NO.) FAULT STP **SWP** A/H NOF REC MAX SWPOA CHG CC REJ DOCKET IN **SWP REL** (NO.) FAULT CAUSE (NO.) FAULT ACTION CONTACT TIME **RESPONSE** (TECHNICIAN) **LIFTUSA** IS **STOPPED** TIME **ACTION** MATERIA GE L USED SWP - Stuck With Passengers, SWPOA - Stuck With Passengers On Arrival, A/H - After Hours, CHG - Chargeable, NOF - No Fault, CC - Call cancelled, STP - Stopped, REC - Only VFM Received Calls, REJ - Only VFM Rejected Calls Lift No. All > 99 GR STP SWP A/H NOF REC MAX SWPOA CHG CC REJ  $\square$ 1178169 08:47 (rahul) lift not working 99 GR (2-13)-S16075) -Elevator> MR>Gear ed 02/04/25 02/04/25 09:40 02/04/25 10:11 (SX) Shaft - Other INDIA4350515 02/04/25 09:40 (K2) Communication Fault (AX) Action - Other 6398892009, 53.0 Minutes (Sanjay Verma) SX: No 6398892009 K2: AX Shaft - Other Communication Fault Elevator running on arrival but some time leval out problem need to be check 1178855 09:08 (Rohit) Lift door issue 04/04/25 Cust omer canc el call 6280985652 0 (Sanjay Verma) : : No

(CALLER) PROBLEM CUSTOM

CALL

CALL	LOGGED		(CALLER) PROBLEM	CUSTOM ER UNIT							
DATE	CONFIRM	OUT	(NO.) FAULT			STP MAX	SWP SWPOA			REC REJ	
DOCKET	IN	SWP REL	(NO.) FAULT CAUSE (NO.) FAULT ACTION								
CONTACT	TIME STOPPED	RESPONSE TIME	(TECHNICIAN) ACTION	IS MATERIA L USED	LIFTUSA GE						
	_		cuck With Passengers Or REC - Only VFM Receive				_	ıble, N	OF - N	lo	
1186480	19:14		(Rahul Kumar) Not working	99 GR (2-13 -S16075) - Elevator> MR>Gear ed		 Ø		_		_⊠_	
27/04/25	27/04/25 20:	31 27/04/25 20:3	36 (SX) Shaft - Other								
INDIA441498	1 27/04/25 20:	33	(K2) Communication Fault (AX) Action - Other								
6398892009, 6398892009	1.4 Hours	1.3 Hours	(Sanjay Verma) SX : K2 : AX Shaft - Other Communication Fault	No							
			Elevator running on arrival foult not found								
1186662	11:20		(rohit) stuck issue .	99 GR (2-13 -S16075) - Elevator> MR>Gear ed					_		
28/04/25	28/04/25 11:	45 28/04/25 13:0	08 (EX) Lift Car - Other					₹			
INDIA441596	6 28/04/25 12:	43	(KZ) Running at Arrival and No Fault Found (AX) Action - Other								
6280985652, 6280985652		1.4 Hours	(Raja .) EX : KZ : AX Lift Car - Other Running at Arrival and No Fault Found								
			Lift Running on arrival no fault found check 30 minutes lift running								

properly